PRODUCT ADVISORY

Data Sheet Specification Change for Intersil Product ISL21007*

Refer to:
PA11068

Date: July 14, 2011

July 14, 2011

To: Our Valued Intersil Customers

Subject: **Data Sheet Specification Change for Intersil Product ISL21007***

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL21007* products. The updates add information to address concerns with potential output voltage drift of the device when exposed to excessive heat or extended temperatures during the board mount operation and the effects of exposure to x-ray sources such as those used for post assembly inspection or airport screening machines. The updated data sheet is available on the Intersil web site at http://www.intersil.com/data/fn/fn6326.pdf. In addition, the data sheet accompanies this advisory as a separate file with the changes shaded in yellow.

Products Affected:

ISL21007BFB812Z	ISL21007BFB830Z-TK	ISL21007CFB830Z	ISL21007DFB825Z-TK
ISL21007BFB812Z-TK	ISL21007CFB812Z	ISL21007CFB830Z-TK	ISL21007DFB825ZS2705
ISL21007BFB820Z	ISL21007CFB812Z-TK	ISL21007DFB812Z	ISL21007DFB830Z
ISL21007BFB820Z-TK	ISL21007CFB820Z	ISL21007DFB812Z-TK	ISL21007DFB830Z-TK
ISL21007BFB825Z	ISL21007CFB820Z-TK	ISL21007DFB820Z	
ISL21007BFB825Z-TK	ISL21007CFB825Z	ISL21007DFB820Z-TK	
ISL21007BFB830Z	ISL21007CFB825Z-TK	ISL21007DFB825Z	

Intersil will take all necessary actions to conform to customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,

Jon Brewster

Jon Brewster
Intersil Corporation PA11068

CC: J. Touvell Q. Harris P. Lee