

[Notes]

R20TS1158EJ0100

Rev.1.00

Jul. 20, 2025

e² studio 2025-07 not compatible with Reality AI Utilities, AI Navigator, QE for Capacitive Touch, QE for AFE and other QE products

Outline

When using either AI-related products or QE products on e² studio, note the following points.

- When using e² studio 2025-07 or later, the following plugins cannot be installed.
 - Reality AI Utilities V2.2.0
 - AI Navigator V2.0.0
 - QE for Capacitive Touch V4.1.0
 - QE for AFE V2.3.0
 - QE for Display[RZ] V3.1.1
 - QE for Camera[RZ] V1.1.1
 - QE for BLE[RL78] [Technical Preview Edition] V1.0.0
 - QE for TCP/IP [Technical Preview Edition] V1.0.1
 - QE for UART [Technical Preview Edition] V1.0.0

1. Note on installation on e² studio 2025-07 or later

1.1 About Reality AI Utilities

1.1.1 Applicable Product

- Reality AI Utilities V2.2.0 or before

1.1.2 Applicable Devices

- RA Family
- RZ Family
- RX Family
- RL78 Family

1.1.3 Details

It fails to install Reality AI Utilities on e² studio installer.

Error message pops up after completing the installation of e² studio.




Figure 1: Error messages after completing to install e² studio

1.1.4 Condition

When installing the relevant product on e² studio 2025-07.

1.1.5 Workaround

Use e² studio 2025-04.1, or wait for the next version for e² studio 2025-07 environment.

1.1.6 Issue Resolution Timeline

This problem will be fixed in the next version. (Scheduled to be released in Aug 2025.)

1.2 About AI Navigator

1.2.1 Applicable Product

- AI Navigator V2.0.0

1.2.2 Applicable Devices

- RA Family (RA8P1)
- RZ/V Series

1.2.3 Detail

It fails to install the AI Navigator on e² studio installer.

1.2.4 Condition

When you try to install the relevant product on e² studio 2025-07.

1.2.5 Workaround

Use suitable version before e² studio 2025-04.1, or wait for the next version for e² studio 2025-07 environment. For detail, please find the Quick Start Guide.

RA : <https://www.renesas.com/document/qsg/renesas-ruhmi-framework-quick-start-guide?r=25565300>

RZ : https://renesas-rz.github.io/rzv_ai_sdk/latest/ainavi_quick_start_guide

1.2.6 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released after July 2025.)

1.3 About QE products

1.3.1 Applicable Products

- QE for Capacitive Touch V4.1.0 or before
- QE for AFE V2.3.0 or before
- QE for Display[RZ] V3.1.1 or before
- QE for Camera[RZ] V1.1.1 or before
- QE for BLE[RL78] [Technical Preview Edition] V1.0.0
- QE for TCP/IP [Technical Preview Edition] V1.0.1 or before
- QE for UART [Technical Preview Edition] V1.0.0

1.3.2 Applicable Devices

- RA Family
- RX Family
- RL78 Family
- RZ Family

1.3.3 Detail

It fails to install the QE products on e² studio installer.

1.3.4 Condition

When you try to install the relevant product on e² studio 2025-07.

1.3.5 Workaround

Use e² studio 2025-04.1 or before, or wait for the next version for e² studio 2025-07 environment.

1.3.6 Issue Resolution Timeline

This problem will be fixed in the next version.

- QE for Capacitive Touch V4.2.0: Scheduled to be released in Aug 2025.
- QE for AFE V2.4.0: Scheduled to be released in Sep 2025.

There are no plans to fix this problem for the following QE products. Please contact us.

- QE for Display[RZ] V3.1.1 or before
- QE for Camera[RZ] V1.1.1 or before
- QE for BLE[RL78] [Technical Preview Edition] V1.0.0
- QE for TCP/IP [Technical Preview Edition] V1.0.1 or before
- QE for UART [Technical Preview Edition] V1.0.0

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.20.2025	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/