RENESAS Tool News

The E10A-USB Emulator Software Revised to V.2.01 Release 00

We have revised the emulator software for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H) to V.2.01 Release 00. These emulators are used for the SuperH RISC engine, H8S, and H8SX families of MCUs.

1. **Versions Concerned**

   Emulator software V1.0.00 through V.2.00 Release 03
   for the E10A-USB emulators (HS0005KCU01H and HS0005KCU02H)

2. **Descriptions of Revision**

   The following devices have been added to the support line of five device groups:

Device Group	MCUs
H8S	H8S/2189RF
H8SX	H8SX/1653F
SH-2	SH7606
SH-4A	SH7763
New_SH-Mobile	SH7343, SH7348

3. **How to Update Your Product**

   (1) If you have not already installed the emulator software for the E10A-USB, execute the Setup.exe file contained in your CD-ROM of the emulator software to install it.

   (2) Download the update program to the E10A-USB emulator software V.2.01 Release 00 device by device from **HERE**.

   (3) Decompress the downloaded ZIP file to obtain the executable of the update program, and then execute it.

(4)   Execute the Setup Tool for E10A-USB Emulator program to set up the emulator software for the E10A-USB.

4. **Notices**

(1)   The update program downloaded in 3-(2) above cannot switch the device group you are using to another one.

(2)   If the update program is executed in the system where the High-performance Embedded Workshop V.4.00.01 or earlier resides, it will be revised to V.4.00.02.