[Upgrade to Revision]

CS+ Device Information for RL78 V8.08.00

Outline

CS+ for CC Device Information for RL78 has been updated from V8.07.01 to V8.08.00.

CS+ for CA,CX Device Information for RL78 has been updated from V8.07.00 to V8.08.00.

1. Items to Be Updated

➢ CS+ for CC Device Information for RL78 V3.00.00 or later

➢ CS+ for CA,CX Device Information for RL78 V3.00.00 or later

➢ CubeSuite+ DevInfo_RL78_78K V1.00.18 or earlier

To check the versions of the above items, visit the web page below and refer to [Components].

https://www.renesas.com/cs+_ver

2. Description

Main changes are as follows. For details, refer to the URL below (information will be uploaded on October 20).

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RL78.html

2.1 Addition of Supported Devices

The following devices are now supported.

- RL78/FGIC

RAJ240310, RAJ240055, RAA240123

2.2 Correction of Device Information

The device information of the following group has been corrected.

- RL78/F24 group

3. Updating the Product

3.1 CS+ V3.00.00 or Later

Update in either of the following ways.

(1) On the windows Start menu, select Programs, Renesas Electronics CS+, and then run the Update Manager (this service will be available from October 20).

Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then start the Update Manager.

If the Rapid Startup function is enabled and the CS+ icon is shown in the Windows notification area, the following error occurs.

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

---

(2) Download and install the desired software tool (tools will be released on October 20) from the URL below.

https://www.renesas.com/us/en/software-tool/cs#download

3.2 CubeSuite+ V2.00.00 to V2.02.00

Refer to 3.1 and update in the same way.

3.3 CubeSuite+ V1.03.00 or Earlier

The Update Manager is not supported.

Download CS+ for CC V8.08.00 or CS+ for CA,CX V4.07.00 from the URL below, install it, and then update the program in the same way as 3.1 above.

https://www.renesas.com/us/en/software-tool/cs#download

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.16.22	-	First edition issued

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,

Koto-ku, Tokyo 135-0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/

TS Colophon 4.3