[Upgrade to Revision]

CS+ Device Information for RL78 V8.09.01

Outline

CS+ for CC Device Information for RL78 has been updated from V8.09.00 to V8.09.01.

CS+ for CA, CX Device Information for RL78 has been updated from V8.08.00 to V8.09.01.

1. Items to Be Updated

➢ CS+ for CC Device Information for RL78 V3.00.00 or later

➢ CS+ for CA, CX Device Information for RL78 V3.00.00 or later

➢ CubeSuite+ DevInfo_RL78_78K V1.00.18 or earlier

To check the versions of the items above, visit the web page below and follow the steps in [Components].

https://www.renesas.com/cs+_ver

2. Description

The following section covers the main update. For details, see the web page below.

(The information is applicable as of April 20.)

https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RL78.html

2.1 Correction of Device Information

The device name of the following group has been corrected:

· RL78/FGIC

 Before correction: RAA240123

 After correction: RAJ240057

RENESAS

3.   Updating the Product

3.1   CS+ V3.00.00 or Later

Update in either of the following ways.

(1)   Open the Windows Start menu, select [Programs], [Renesas Electronics CS+], and then run Update Manager. (The service is available as of April 20.)

> **Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then run Update Manager.**
> **If the Rapid Startup function is enabled and CS+ is shown in the Windows notification area, the following error message appears.**

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

---

(2)   Download and install the desired software tool from the link below.

(Tools are available as of April 20.)

https://www.renesas.com/us/en/software-tool/cs#download

3.2   CubeSuite+ V2.00.00 to V2.02.00

See 3.1 and update in the same way.

3.3   CubeSuite+ V1.03.00 or Earlier

Update Manager does not support CubeSuite+ V1.03.00 and earlier.

Download and install CS+ for CC V8.09.00 or CS+ for CA, CX V4.08.00 from the link below, and then update the program as shown in 3.1 above.

https://www.renesas.com/us/en/software-tool/cs#download

Revision History

Rev.	Date	Page	Summary
		Description	
1.00	Apr.16.23	-	First edition issued

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/