[Upgrade to revision]

e^2 studio Smart Configurator Plug-in V2.8.0,

RX Smart Configurator V2.8.0

Overview

The products in the title will be revised and their version numbers will be changed as follows:

(1) e^2 studio Smart Configurator Plug-in: V2.7.0 to V2.8.0

(2) RX Smart Configurator: V2.7.0 to V2.8.0

1. Version to Be Updated

➢ All revisions up to 2020-10 of e^2 studio (V2.7.0 of Smart Configurator Plug-in)

➢ All revisions up to V2.7.0 of RX Smart Configurator

2. Items Revised

The major revision points are as follows. Refer to the following release note for details.

➢ RX Smart Configurator

Smart Configurator for RX V2.8.0 Release Note. This information will be released on January 20.

https://www.renesas.com/software-tool/smart-configurator#documents

2.1 Description of Modification

The problems regarding the points below have been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0623ES0100

1. When using "r_sci_rx" component and making pin configurations for RXD and TXD

Applicable devices: RX651, RX65N, RX66N, RX72M and RX72N groups

2. When using "r_sci_rx" component, duplicate SCI11 channels are displayed in the Components configuration panel

Applicable devices: RX66N, RX72M and RX72N groups

For details about the problems, refer to the following URL:

https://www.renesas.com/document/tnn/notes-e-studio-smart-configurator-plug-smart-configurator-rx-12

(2) RENESAS TOOL NEWS, Document No. R20TS0638ES0100

    1. Note on setting timer operation period in Motor component

      Applicable devices: RX13T, RX23T, RX24T, RX24U, RX66T, RX72T, and RX72M groups

    2. When loading project with port configuration created in V2.5.0 or version before into V2.6.0 version onwards

      Applicable devices: RX651 and RX65N groups

      For details about the problems, refer to the following URL:

      https://www.renesas.com/document/tnn/notes-e-studio-smart-configurator-plug-smart-configurator-rx-14

3.   How to Update Your Copy

The method of updating depends on the product you are using.

For details, refer to the following. The updates are available free of charge.

3.1   For e^2 studio

For the method of updating e^2 studio, refer to section 3, "Updating Your Product" in the following Tool News. This information will be released on January 20.

https://www.renesas.com/software-tool/e-studio#documents

RENESAS TOOL NEWS, January 16, Document No. R20TS0643E0100

[Upgrade to version] e^2 studio Integrated Development Environment 2021-01

Note that by updating e^2 studio, the Smart Configurator will also be updated.

3.2   For CS+

To update your program, use either of the following methods:

(1)   For online updating of CS+, refer to section 4, "How to Update Your Copy" in the following Tool News. This information will be released on January 20.

https://www.renesas.com/software-tool/cs#documents

RENESAS TOOL NEWS, January 16, Document No. R20TS0648E0100

[Upgrade to revision] CS+ Integrated Development Environment V8.05.00

(2)   Download RX Smart Configurator from the following URL, and then install the program.

   The program will be available from January 20.
https://www.renesas.com/software-tool/smart-configurator#documents

Smart Configurator for RX V2.8.0

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jan.16.21	-	First edition issued

Corporate Headquarters

Contact information

Trademarks