RENESAS Tool News

The Emulator Software for the E6000H Emulators Specific to the H8SX MCU Family Revised to V.4.06 Release 00

We have revised the emulator software for the E6000H emulators specific to the H8SX MCU family from V.4.05 Release 00 to V.4.06 Release 00.

1. Product Concerned
HS1650EPH60H

2. Description of Revision
The following MCU has been added to the support line:
H8SX/1650C

3. How to Update Your Product
On-line update is available free of charge. Update yours in either of the following ways:
(1) Use AutoUpdate Utility. This service will be available on and after August 6.
(2) Download the update program of the V.4.06 Release 00 product from the Web site at:
      http://www.renesas.com/e6000h_download
Then execute it. This Web site will be opened from August 5 on.
The above URL is one of our global sites (in English).

4. Notice
If the update program is executed in the development system where High-performance Embedded Workshop V.4.02.00 or earlier resides, it will be updated to V.4.04.01.

included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.