PRODUCT ADVISORY

Minimum Line Quantity Changes for Listed Intersil Products

Refer to:
PA14064

Date: December 19, 2014

intersil™

December 19, 2014

To: Our Valued Intersil Customers

Subject: **Minimum Line Quantity Change**

This advisory is to inform you that Intersil has updated the minimum line quantity (MLQ) for the parts listed in this notice. This notice is distributed for information only as the change does not affect product form, fit or function.

A product list, citing the old and new MLQ (minimum order quantity) is included in this notice. These changes will be implemented on February 1, 2015.

These changes will affect all orders placed on the books on or after February 1, 2015 but will not affect any orders currently on the books or placed on the books prior to that date.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,

Jeffrey Touvell

Intersil Corporation PA14064

CC: B. Everling R. Pitts R. Velliquette P. Graves

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
24502BVA	20	40
29104BJA	10	30
5962-0620701Q3A	43	172
5962-0620702Q3A	43	129
5962-0620703Q2A	112	168
5962-0620704Q2A	112	168
5962-0620705Q3A	43	172
5962-0620706Q3A	43	172
5962-0620707Q2A	112	224
5962-0620708Q2A	112	168
5962-0623501QPC	48	100
5962-0623502QPC	48	100
5962-0623601QPC	48	100
5962-0623602QPC	48	100
5962-0625501QXC	30	100
5962-8501601YA	39	78
5962-85016023A	37	43
5962-8501602YA	39	65
5962-8512704XA	13	39
5962-85131013A	23	66
5962-8513101XA	39	78
5962-85131023A	22	43
5962-8513102XA	39	65
5962-8513103EA	75	150
5962-85131073A	43	86
5962-8513107XA	78	156
5962-85131092A	112	168
5962-8671601EA	125	300
5962-86860012A	56	168
5962-8686001EA	50	100
5962-8687901EA	46	115
5962-8688001QA	18	45
5962-8757701RA	38	76
5962-8757702RA	38	76
5962-8778301EA	125	300
5962-8778701CA	125	150
5962-8850201CA	75	175
5962-8869002JA	30	60
5962-8950201GC	57	100
5962-8954801GC	72	100

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
5962-8954801PA	96	192
5962-89620012A	56	112
5962-8963501PA	144	192
5962-89636012A	56	224
5962-8963601GC	36	70
5962-8963601PA	96	144
5962-9051801MEA	75	200
5962-9052501MQA	99	207
5962-9052502MQA	36	72
5962-9054302MQA	18	45
5962-9054901MQA	9	18
5962-9073101MEA	500	1000
5962-9088801MRA	57	171
5962-9204201MEA	175	500
5962-9204201MEAS2035	175	350
5962-9467701M2A	56	112
77052012A	112	168
7705202EA	75	200
7705202EAS2035	75	175
7705202EAS2461	25	175
7705302EA	300	900
7800302GC	40	100
7800302PA	144	288
78029013A	6	10
7802901JA	15	30
8001601CA	50	75
81006122A	56	112
8100617EA/MLB	75	125
81006222A	56	112
8403602JA	30	60
8403603JA	45	75
8403606JA	30	60
8405202QA	9	27
84065013A	43	63
8406501JA	45	105
8406602QA	45	108
8406602XA	30	60
8406701RA	38	76
8406801VA	40	100
8406901RA	19	38

intersil™

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
85015013A	20	43
8501501XA	26	52
CDP1802ACD3	36	63
DG411AK/883	500	1000
HA1-2400/883	150	300
HA1-2420-2	75	200
HA1-4900-2	100	200
HA1-4902/883	50	100
HA1-4902-2	150	300
HA1-5104/883	100	200
HA1-5104-2	175	450
HA1-5320-2	125	250
HA2-2510/883	60	100
HA2-2520-2	100	200
HA2-2522-2	100	200
HA2-2600-2	100	200
HA2-2640-2	100	200
HA2-2640-2ZR5254	100	200
HA2-5002-2	100	200
HA2-5002-2ZR5254	100	200
HA2-5033-2	72	144
HA2-5127/883	38	70
HA4-5002/883	112	168
HA7-2510/883	144	288
HA7-2520-2	240	576
HA7-2640-2	240	528
HA7-5101/883	144	240
HA7-5102-2	240	576
HA7-5147-2	192	432
HA7-5147R5254	192	384
HD1-15530-8	15	30
HD1-4702/883	100	200
HD1-6402B/883	45	81
HD1-6402R/883	99	198
HD1-6409/883	57	114
HI1-0201/883	325	650
HI1-0201-2	500	1500
HI1-0201HS/883	225	500
HI1-0201HS-2	200	500
HI1-0303/883	150	500

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
HI1-0303/883R5507	150	500
HI1-0303-2	525	1500
HI1-0303R5254	1000	1500
HI1-0390-2	150	400
HI1-0506-2	143	299
HI1-0506A-2	91	195
HI1-0506A-8	65	130
HI1-0507-2	286	572
HI1-0508/883	250	500
HI1-0508-2	500	1000
HI1-0508A-8	125	225
HI1-0509-2	250	600
HI1-0509A-2	150	350
HI1-0509A-8	125	250
HI1-0546/883	52	114
HI1-0546-2	143	286
HI1-0547/883	52	104
HI1-0548/883	100	200
HI1-0548-2	150	350
HI1-0549/883	100	200
HI1-0549-2	175	400
HI1-1818A-2	150	400
HI1-5042-2	250	600
HI1-5043-2	125	300
HI1-5046A/883	100	200
HI1-5051-2	125	300
HI1-565ATD-2	45	60
HI1-574ASD-2	52	78
HI1-574ATD-2	26	52
HI1-674ATD/883	26	39
HI4-0546/883	43	64
HI4-0548/883	56	112
HI4-5051/883	56	112
HM1-6514/883	80	200
HM1-6514B/883	60	120
HM1-65162/883	45	75
HM1-65162C/883	45	135
HM1-6551B/883	51	136
HM1-65642/883	26	52
HM1-65642B/883	26	39

PA14064 Minimum Line Quantity

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
HM1-6617/883	30	45
HM1-6642B/883	30	90
HS1-3182-8	92	161
HS1-3182-9+	69	138
HS1-3282-8	45	135
HS4-3182-8	43	129
ICL3221EMVZ	1920	4800
ICL3221EMVZ-T	2500	5000
ISL22316WMUEP	200	3000
ISL22316WMUEP-TK	1000	3000
ISL22326WMVEP	384	1536
ISL22326WMVEP-TK	1000	2000
ISL22346WMVEP	296	814
ISL3178AEMBZ	980	1960
ISL3282EMRTEP-TK	1000	3000
ISL3298EMRTEP-TK	1000	3000
ISL6406MVEP	384	2112
ISL6406MVEP-TK	1000	3000
ISL8560MREP	200	1000
ISL9000AMRNCEP	400	3000
ISL9000AMRNCEP-TK	1000	3000
ISLA112P25MREP	32	69
JM38510/12202BGA	20	50

Marketing Part Number	Current MLQ (MOQ)	New MLQ (MOQ)
JM38510/12203BGA	30	60
JM38510/12204BGA	30	60
JM38510/12205BGA	30	60
JM38510/12206BGA	30	60
JM38510/19001BXA	52	117
JM38510/19002BXA	39	78
JM38510/19004BXA	26	52
JM38510/19005BEA	50	75
JM38510/19006BEA	50	100
JM38510/19007BEA	100	250
JM38510/19008BEA	100	250
MD80C86-2/883	9	27
MD80C86-2/B	18	27
MD80C88/B	18	27
MD80C88-2/883	9	18
MD82C37A/B	18	45
MD82C52/B	39	65
MD82C54/B	45	105
MD82C55A/B	54	108
MD82C84A/B	60	100
MD82C88/B	38	57
MD82C89/B	19	38