RENESAS Tool News

Note on Using Development Tools for R8C/3MQ Group of MCUs

When using the development tools for R8C/3MQ group of MCUs, take note of the following problem:

- With the usage of the development tools in accordance with changing the specifications of R8C/3MQ group of MCUs

1. Products and Versions Concerned

- R8C E8a Emulator Debugger V.1.05.00 and later
which are included in E8a Emulator Software V.1.05 Release 00 or later
- R8C E1/E20 Emulator Debugger V.1.01.00 and later
- C/C++ compiler package for the M16C series, R8C family (M3T-NC30WA)
  V.5.42 Release 00 and later

2. Description

The program ROM size of R5F213MCQNNP in R8C/3MQ group has been changed.
And the restriction on the use of the data flash of all MCUs in R8C/3MQ
group has been published.
In accordance with the above changes, take note of the problem in using
the products concerned.

For details of the changed specifications of the MCUs in R8C/3MQ group
and how to use the products concerned, see Renesas Technical Update
Document No. TN-R8C-A028A/E at:
https://www.renesas.com/search/keyword-
search.html#genre=document&q=TN-R8C-A028A/E

3. Schedule of Fixing the Problem

Sorry we have no plan to fix this problem in the emulator debuggers and

compiler package.

[Disclaimer]