Condition1: CPU Clock=Main, Division Ratio=1/8, XIN Drive Capacity=High, XCIN Drive Capacity=High, Pheripheral Function=Not operating, Software Wait=0-wait

Vcc-Icc (During Reset)

Type No.M30624MGM , f(Xin)=10MHz , Topr=25 degrees C , Condition 1

Caution: This data is not guaranteed value.