RENESAS Tool News

The AutoUpdate Utility Revised to V.1.01.00

We have revised the AutoUpdate utility, an expanded function of the High- Performance Embedded Workshop, from V.1.00.02 to V.1.01.00.

1. **Versions to Be Revised**

   The AutoUpdate Utility V.1.00.00, V.1.00.01, and V.1.00.02

   The above versions of the software are bundled with the High-Performance Embedded Workshop V.4.00.00 through V.4.00.03. *

   * To check for the version number of your High-performance Embedded Workshop, open the Help menu and select the About High-performance Embedded Workshop command.

2. **Descriptions of Revision**

   2.1 Functions Introduced and Improved

   (1) The application programs selected as the objects of auto-update are saved in this utility program.

   (2) A function has been introduced which selects and deselects all of the detected updates at a time.

   (3) Improvements have been made to the displays of character strings in the AutoUpdate wizard dialog box and the way of presenting the detected updates on-screen.

   2.2 A Problem Resolved

   The problem that Japanese characters get garbled in the AutoUpdate wizard dialog box has been resolved (This

problem arises on Japanese version only).

3. **How to Update Your Product**

   Update yours using the AutoUpdate Utility in your High-Performance Embedded Workshop. The updater to revise this program will be available on and after June 20. Then the AutoUpdate utility detects the updater.

[Disclaimer]