RENESAS Tool News

Code Generator for the RL78, 78K0R, and 78K0 MCUs, Which is Used with CubeSuite+, Revised

We have revised the code generator for the RL78, 78K0R, and 78K0 MCUs, "CubeSuite+ Code_Generator for RL78_78K," from V1.00.01 to V1.00.02.

This tool, which is included in the CubeSuite+ package, is used with CubeSuite+ to generate device drivers for controlling peripherals of the RL78, 78K0R, and 78K0 MCUs.

1. Product to Be Updated

CubeSuite+ Code_Generator for RL78_78K V1.00.01

To check to see the version number of your product, follow these steps:
(1) On Windows XP
   (1.1) Open the Add/Remove Programs list in Windows Control Panel.
   (1.2) Click the icon of CubeSuite+ Code_Generator for RL78_78K.
   (1.3) Then click "Click here for support information."

(2) On Windows Vista and Windows 7
   (2.1) Open "Programs and Features" in Windows Control Panel.
   (2.1) Check the version number of CubeSuite+ Code_Generator for
       RL78_78K in the list.

2. Descriptions of Revision

(1) The following MCUs of the RL78 family have been supported:
    - RL78/G14 and RL78/I1A groups

(2) The code generated for the following MCUs of the RL78 family has
    been revised:
    - RL78/G13 group

For details, see the release note at:

http://www.renesas.com/products/tools/ide/ide_cubesuite_plus/Documentation.jsp
This release note will be published on October 7, 2011.

You can also see the descriptions of revision at:

http://www.renesas.com/cubesuite+/CubeSuitePlus_Code_Generator_for_RL78_78K.html

This page will be opened on October 7, 2011.

3. Notice

To use CubeSuite+ Code_Generator for RL78_78K V1.00.02, you must update
your CubeSuite+ to V1.00.02. For information about this revised product,
see RENESAS TOOL NEWS Document No. 111005/tn1 at:
http://tool-support.renesas.com/eng/toolnews/111005/tn1.htm
This page will be available on October 7, 2011.

4. Updating Your Product

Online update is available free of charge. The methods of update are
depending on the edition of your CubeSuite+.

4.1 For Commercial Edition of CubeSuite+
To update yours, use either of the following methods:
(1) On the Start menu, select Programs and then Renesas Electronics
CubeSuite+ to start the Update Manager.
This service will be provided from October 7.

(2) Download CubeSuite+ Code_Generator for RL78_78K V1.00.02 at:
http://www.renesas.com/cubesuite+_download
Then install it. The installer will be published in this Web site
on October 7.
The above URL is one of our global sites.

4.2 For Free-of-Charge Evaluation Edition of CubeSuite+
Use the method (2) in 4.1 above.

---

be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.