RENESAS Tool News

RENESAS TOOL NEWS on January 16, 2016: 160116/tn3

Device Information (Managed by CS+) for RH850 Family Revised to V3.00.04

We are revising the device information file (managed by CS+) for the RH850 family of MCUs and accordingly will change the version number from 3.00.03 to 3.00.04.

---

1. Product and Versions to Be Updated
   (1) Device information file managed by CS+ for the RH850 family of MCUs
   (CS+ Device Information for RH850) V3.00.00 or later
   (2) Device information file managed by CubeSuite+ for the RH850 family
   of MCUs (CubeSuite+ DevInfo_RH850) V1.00.04 or earlier

   Check your version number of "CS+ Device Information for RH850" or "CubeSuite+ DevInfo_RH850" with reference to the procedure described under the heading "Components" at the URL below.
   https://www.renesas.com/cs+_ver

2. Descriptions of Revision
   (1) Addition of Supported MCUs
   The following groups have been added to the set of supported MCUs.
   - RH850/F1K group*
   - RH850/D1M group

   *: Only the simulator can be used in the evaluation of debugging. The E1 and E20 emulators will not be usable with the RH850/F1K group until we separately announce that this is possible. Operation is not guaranteed in case of an attempt to run a project created for the RH850/F1K on a different MCU.

   (2) Correction to SFR Information
   SFR information for the groups listed below will be corrected.
   - RH850/F1L group
   - RH850/P1M group

- RH850/D1L group
- RH850/D1M group
- RH850/F1H group

For details, go to:
http://www.renesas.com/cubesuite+/CubeSuitePlus_DevInfo_RH850.html
This information will be available from January 20.

3. Updating Your Product

Online updating is available free of charge.
To update either your commercial edition or evaluation edition of CS+, use either of the following methods.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

(1) On the "Start" menu, select "Programs" and then "Renesas Electronics CS+" to start the Update Manager.
This service will be available from January 20.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.
If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

```
----------
M0120001
Installation is suspended because "CubeSuiteW+.exe" is running. It will be resumed next time you start the tool.
----------
```

(2) Download and install V3.00.04 of device information file managed by CS+ for the RH850 family of MCUs from the following URL.
https://www.renesas.com/cs+_download
The program will be available from January 20.

3.2 For CubeSuite+ V2.02.01 and Earlier Versions

Please download and install the evaluation edition of CS+ V3.03.00 from the following URL:
https://www.renesas.com/cs+_download
Then, update your program by using the method in 3.1 (1) or (2) above.

[Disclaimer]
The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.