Change PLP Products List

Change PLP products will be listed internet site for about three months following the date of the charge.

Jun. 30, 2024

No	Registration	PLP Status	Product	L1 Layer Name	L2 Layer Name	L3 Layer Name	L4 Layer Name	Part Name	PLP Orderable Part Name (before)	PLP Orderable Part Name (after)	Equivalent or Similar	PLP Termination date	PLP Termination date (after)	Remarks	History	Update
0001	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51101ADFK	R5F51101ADFK#30	R5F51101ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0002	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51101ADFL	R5F51101ADFL#30	R5F51101ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0003	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51101ADFM	R5F51101ADFM#30	R5F51101ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0004	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFK	R5F51103ADFK#30	R5F51103ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0005	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFL	R5F51103ADFL#30	R5F51103ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0006	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFM	R5F51103ADFM#30	R5F51103ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0007	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51104ADFK	R5F51104ADFK#30	R5F51104ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0008	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51104ADFL	R5F51104ADFL#30	R5F51104ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0009	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51104ADFM	R5F51104ADFM#30	R5F51104ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0010	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51105ADFK	R5F51105ADFK#30	R5F51105ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0011	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51105ADFL	R5F51105ADFL#30	R5F51105ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0012	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51105ADFM	R5F51105ADFM#30	R5F51105ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0013	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFK	R5F51103ADFK#30	R5F51103ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0014	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFL	R5F51103ADFL#30	R5F51103ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0015	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX110	R5F51103ADFM	R5F51103ADFM#30	R5F51103ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0016	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFK	R5F51111ADFK#3A	R5F51111ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0017	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFL	R5F51111ADFL#3A	R5F51111ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0018	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFM	R5F51111ADFM#3A	R5F51111ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0019	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51113ADFK	R5F51113ADFK#3A	R5F51113ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0020	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51113ADFL	R5F51113ADFL#3A	R5F51113ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0021	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51113ADFM	R5F51113ADFM#3A	R5F51113ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0022	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51114ADFK	R5F51114ADFK#3A	R5F51114ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0023	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51114ADFL	R5F51114ADFL#3A	R5F51114ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0024	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51114ADFM	R5F51114ADFM#3A	R5F51114ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0025	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51115ADFK	R5F51115ADFK#3A	R5F51115ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0026	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51115ADFL	R5F51115ADFL#3A	R5F51115ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0027	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51115ADFM	R5F51115ADFM#3A	R5F51115ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0028	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51116ADFK	R5F51116ADFK#3A	R5F51116ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0029	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51116ADFL	R5F51116ADFL#3A	R5F51116ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0030	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51116ADFM	R5F51116ADFM#3A	R5F51116ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0031	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51117ADFK	R5F51117ADFK#3A	R5F51117ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0032	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51117ADFL	R5F51117ADFL#3A	R5F51117ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0033	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51117ADFM	R5F51117ADFM#3A	R5F51117ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0034	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51118ADFK	R5F51118ADFK#3A	R5F51118ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0035	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51118ADFL	R5F51118ADFL#3A	R5F51118ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0036	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51118ADFM	R5F51118ADFM#3A	R5F51118ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0037	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFK	R5F51111ADFK#3A	R5F51111ADFK#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0038	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFL	R5F51111ADFL#3A	R5F51111ADFL#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0039	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX111	R5F51111ADFM	R5F51111ADFM#3A	R5F51111ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0040	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51135ADFM	R5F51135ADFM#3A	R5F51135ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0041	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51135ADFP	R5F51135ADFP#3A	R5F51135ADFP#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0042	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51136ADFM	R5F51136ADFM#3A	R5F51136ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0043	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51136ADFP	R5F51136ADFP#3A	R5F51136ADFP#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0044	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51137ADFM	R5F51137ADFM#3A	R5F51137ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0045	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51137ADFP	R5F51137ADFP#3A	R5F51137ADFP#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0046	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51138ADFM	R5F51138ADFM#3A	R5F51138ADFM#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0047	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX113	R5F51138ADFP	R5F51138ADFP#3A	R5F51138ADFP#1A			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0048	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51303ADFK	R5F51303ADFK#30	R5F51303ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0049	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51303ADFL	R5F51303ADFL#30	R5F51303ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0050	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51303ADFM	R5F51303ADFM#30	R5F51303ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0051	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51303ADFN	R5F51303ADFN#30	R5F51303ADFN#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0052	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51305ADFK	R5F51305ADFK#30	R5F51305ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0053	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51305ADFL	R5F51305ADFL#30	R5F51305ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0054	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51305ADFM	R5F51305ADFM#30	R5F51305ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0055	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51305ADFN	R5F51305ADFN#30	R5F51305ADFN#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0056	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51306BDFK	R5F51306BDFK#30	R5F51306BDFK#10	Equivalent		Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0057	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51306BDFL	R5F51306BDFL#30	R5F51306BDFL#10	Equivalent		Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0058	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51306BDFM	R5F51306BDFM#30	R5F51306BDFM#10	Equivalent		Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0059	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51306BDFN	R5F51306BDFN#30	R5F51306BDFN#10	Equivalent		Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0060	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51306BDFP	R5F51306BDFP#30	R5F51306BDFP#10	Equivalent		Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0061	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51307ADFK	R5F51307ADFK#30	R5F51307ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0062	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51307ADFP	R5F51307ADFP#30	R5F51307ADFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0063	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51308ADFK	R5F51308ADFK#30	R5F51308ADFK#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0064	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51308ADFL	R5F51308ADFL#30	R5F51308ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0065	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51308ADFM	R5F51308ADFM#30	R5F51308ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0066	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51308ADFN	R5F51308ADFN#30	R5F51308ADFN#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0067	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX100	RX130	R5F51308ADFP	R5F51308ADFP#30	R5F51308ADFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0068	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52103BDFL	R5F52103BDFL#30	R5F52103BDFL#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0069	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52103BDFM	R5F52103BDFM#30	R5F52103BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0070	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52104BDFL	R5F52104BDFL#30	R5F52104BDFL#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0071	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52104BDFM	R5F52104BDFM#30	R5F52104BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0072	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52105BDFB	R5F52105BDFB#30	R5F52105BDFB#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0073	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52105BDFL	R5F52105BDFL#30	R5F52105BDFL#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0074	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52105BDFM	R5F52105BDFM#30	R5F52105BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0075	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52105BDFN	R5F52105BDFN#30	R5F52105BDFN#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0076	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52105BDFP	R5F52105BDFP#30	R5F52105BDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0077	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52106BDFB	R5F52106BDFB#30	R5F52106BDFB#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0078	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52106BDFL	R5F52106BDFL#30	R5F52106BDFL#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0079	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52106BDFM	R5F52106BDFM#30	R5F52106BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0080	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52106BDFN	R5F52106BDFN#30	R5F52106BDFN#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0081	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52106BDFP	R5F52106BDFP#30	R5F52106BDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0082	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52107BDFB	R5F52107BDFB#30	R5F52107BDFB#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0083	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52107CDFM	R5F52107CDFM#30	R5F52107CDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0084	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52107CDFN	R5F52107CDFN#30	R5F52107CDFN#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0085	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52107CDFP	R5F52107CDFP#30	R5F52107CDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0086	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108BDFB	R5F52108BDFB#30	R5F52108BDFB#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0087	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108CDFF	R5F52108CDFF#V0	R5F52108CDFF#H0			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0088	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108CDFM	R5F52108CDFM#30	R5F52108CDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0089	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108CDFN	R5F52108CDFN#30	R5F52108CDFN#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0090	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108CDFP	R5F52108CDFP#30	R5F52108CDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0091	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108ABDFB	R5F52108ABDFB#30	R5F52108ABDFB#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0092	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108ABDFP	R5F52108ABDFP#30	R5F52108ABDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0093	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108BDFB	R5F52108BDFB#30	R5F52108BDFB#10			Mar, 2031	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0094	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX210	R5F52108BDFP	R5F52108BDFP#30	R5F52108BDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0095	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX21A	R5F521A6BDFM	R5F521A6BDFM#30	R5F521A6BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0096	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX21A	R5F521A6BDFN	R5F521A6BDFN#30	R5F521A6BDFN#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0097	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX21A	R5F521A6BDFP	R5F521A6BDFP#30	R5F521A6BDFP#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0098	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX21A	R5F521A7BDFM	R5F521A7BDFM#30	R5F521A7BDFM#10			Dec, 2027	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0099	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX21A	R5F521A7BDFN	R5F521A7BDFN#30	R5F521A7BDFN#10			Dec, 2027	Switch to full carton products	PLP

Change PLP Products List

Change PLP products will be listed internet site for about three months following the date of the charge.

Jun. 30, 2024

No	Registration	PLP Status	Product	L1 Layer Name	L2 Layer Name	L3 Layer Name	L4 Layer Name	Part Name	PLP Orderable Part Name (before)	PLP Orderable Part Name (after)	Equivalent or Similar	PLP Termination date	PLP Termination date (after)	Remarks	History	Update
0128	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318ADFL	R5F52318ADFL#30	R5F52318ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0129	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318ADFM	R5F52318ADFM#30	R5F52318ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0130	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318ADFP	R5F52318ADFP#30	R5F52318ADFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0131	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318BDFL	R5F52318BDFL#30	R5F52318BDFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0132	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318BDFM	R5F52318BDFM#30	R5F52318BDFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0133	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX231, RX230	R5F52318BDFP	R5F52318BDFP#30	R5F52318BDFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0134	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23E-A	R5F523E5ADFL	R5F523E5ADFL#30	R5F523E5ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0135	2020	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23E-A	R5F523E6ADFL	R5F523E6ADFL#30	R5F523E6ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0136	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3ADFD	R5F523T3ADFD#30	R5F523T3ADFD#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0137	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3ADFL	R5F523T3ADFL#30	R5F523T3ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0138	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3ADFM	R5F523T3ADFM#30	R5F523T3ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0139	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3AGFD	R5F523T3AGFD#30	R5F523T3AGFD#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0140	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3AGFL	R5F523T3AGFL#30	R5F523T3AGFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0141	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T3AGFM	R5F523T3AGFM#30	R5F523T3AGFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0142	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5ADFD	R5F523T5ADFD#30	R5F523T5ADFD#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0143	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5ADFL	R5F523T5ADFL#30	R5F523T5ADFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0144	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5ADFM	R5F523T5ADFM#30	R5F523T5ADFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0145	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5AGFD	R5F523T5AGFD#30	R5F523T5AGFD#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0146	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5AGFL	R5F523T5AGFL#30	R5F523T5AGFL#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0147	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX23T	R5F523T5AGFM	R5F523T5AGFM#30	R5F523T5AGFM#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0148	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524T8ADFF	R5F524T8ADFF#31	R5F524T8ADFF#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0149	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524T8ADFM	R5F524T8ADFM#31	R5F524T8ADFM#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0150	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524T8ADFN	R5F524T8ADFN#31	R5F524T8ADFN#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0151	2019	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524T8ADFP	R5F524T8ADFP#31	R5F524T8ADFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0152	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TAADFF	R5F524TAADFF#31	R5F524TAADFF#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0153	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TAADFM	R5F524TAADFM#31	R5F524TAADFM#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0154	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TAADFN	R5F524TAADFN#31	R5F524TAADFN#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0155	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TAADFP	R5F524TAADFP#31	R5F524TAADFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0156	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TBADFP	R5F524TBADFP#31	R5F524TBADFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0157	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TCADFP	R5F524TCADFP#31	R5F524TCADFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0158	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24T	R5F524TEADFP	R5F524TEADFP#31	R5F524TEADFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0159	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24U	R5F524UBADFB	R5F524UBADFB#30	R5F524UBADFB#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0160	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24U	R5F524UBADFP	R5F524UBADFP#30	R5F524UBADFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0161	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24U	R5F524UEADFB	R5F524UEADFB#30	R5F524UEADFB#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0162	2018	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX200	RX24U	R5F524UEADFP	R5F524UEADFP#30	R5F524UEADFP#10			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0163	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MFDDFB	R5F564MFDDFB#31	R5F564MFDDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0164	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MFDDFP	R5F564MFDDFP#31	R5F564MFDDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0165	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MFHDFC	R5F564MFHDFC#31	R5F564MFHDFC#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0166	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MFHDFP	R5F564MFHDFP#31	R5F564MFHDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0167	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MGCDFB	R5F564MGCDFB#31	R5F564MGCDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0168	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MGCDFC	R5F564MGCDFC#31	R5F564MGCDFC#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0169	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MGHDFB	R5F564MGHDFB#31	R5F564MGHDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0170	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MGHDFC	R5F564MGHDFC#31	R5F564MGHDFC#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0171	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MGHDFP	R5F564MGHDFP#31	R5F564MGHDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0172	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJCDFB	R5F564MJCDFB#31	R5F564MJCDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0173	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJCDFP	R5F564MJCDFP#31	R5F564MJCDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0174	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJGDFB	R5F564MJGDFB#31	R5F564MJGDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0175	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJHDFB	R5F564MJHDFB#31	R5F564MJHDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0176	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJHDFC	R5F564MJHDFC#31	R5F564MJHDFC#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0177	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MJHDFP	R5F564MJHDFP#31	R5F564MJHDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0178	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLCDFB	R5F564MLCDFB#31	R5F564MLCDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0179	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLCDFP	R5F564MLCDFP#31	R5F564MLCDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0180	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLDDFB	R5F564MLDDFB#31	R5F564MLDDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0181	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLDDFC	R5F564MLDDFC#31	R5F564MLDDFC#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0182	2018	2_Continuation(Changed P/N)	MCU/SOC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLGDFP	R5F564MLGDFP#31	R5F564MLGDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0183	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLHDFB	R5F564MLHDFB#31	R5F564MLHDFB#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024
0184	Before 2016	2_Continuation(Changed P/N)	MCU/SoC	Microcontrollers (MCU) and Microprocessors (MPU)	RX Family	RX600	RX64M	R5F564MLHDFP	R5F564MLHDFP#31	R5F564MLHDFP#11			Dec, 2038	Switch to full carton products	PLP Inspection on Jun , 2024	Jun, 2024