RENESAS TOOL NEWS on October 1, 2014: 141001/tn12

Applilet3 for V850, Applilet3 for RL78, and Applilet3 for 78K Revised

We have revised the Applilet3 for V850, the Applilet3 for RL78, and the Applilet3 for 78K.

1. Products and Versions Concerned
   The three Applilet3 products have been revised as follows:
   (1) Applilet3 for V850
       from V1.00.00 to V1.01.00
   (2) Applilet3 for RL78
       from V1.05.00 to V1.06.00
   (3) Applilet3 for 78K
       from V1.01.00 to V1.02.00

2. Description of Revision
2.1 Applilet3 for V850
   We have revised the common program of Applilet3 and according to
   this revision, we have given a new version to the product.
   This updating has associated with the updating to CS+ from CubeSuite+,
   there is no change in the function.

2.2 Applilet3 for RL78
   (1) Updating
       We have revised the common program of Applilet3 and according to
       this revision, we have given a new version to the product.
       This updating has associated with the updating to CS+ from
       CubeSuite+, there is no change in the function.

   (2) A Problem Fixed
       The following problem, of which we informed you in RENESAS TOOL NEWS
       Document No. 140816/tn6, has been fixed:

       - With setting of port 1 (target: RL78/G14 group)
       For details of the problem, see the following page:
       https://www.renesas.com/search/keyword-
       search.html#genre=document&q=140816tn6

2.3 Applilet3 for 78K
   We have revised the common program of Applilet3 and according to
   this revision, we have given a new version to the product.
   This updating has associated with the updating to CS+ from CubeSuite+,
   there is no change in the function.

3. Updating Your Product
   Download the installers of the products from the following URL:

    https://www.renesas.com/applilet_download
   The installers will be available on this site from October 6.