[Notes]
PG-FP6 Flash Memory Programmer
(RH850/U2A16 Group)

Outline

When using the PG-FP6 flash memory programmer, note the following point.

1. RH850/U2A16 group

1. RH850/U2A16 Group

1.1 Applicable Product

Programming GUI for PG-FP6 (FP6 Terminal) V1.06.00

1.2 Applicable Devices

RH850 family RH850/U2A16 group: R7F702300

RH850 family: R7F702Z19A

1.3 Details

If "Override SVR parameters" of "RH850 SVR Settings" is unchecked, the SVR parameters, which are written to the option bytes while establishing a connection to the device, are not applied to the device properly. Therefore, execution of a command might cause an error.

1.4 Workaround

Use Programming GUI for PG-FP6 (FP6 Terminal) V1.05.03.

1.5 Schedule for Fixing the Problem

The problem will be fixed in Programming GUI for PG-FP6 (FP6 Terminal) V1.06.01.

(Scheduled to be released on Jan. 20th, 2022)

Revision History

Rev.	Date	Description	
		Page	**Summary**
1.00	Dec.01.21	-	First edition issued

TS Colophon 4.2