To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

RENESAS

RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan
RenesasTechn ology Corp.

Product Category	User Development Environment			Document No.	TN-OS*- A085A/E	Rev.	1.0
Title	HI7700/4 V.1.03 Release 01 Updates			Information Category	Technical Notification		
Applicable Product	Show below	Lot No.		Reference Document	HI7000/4 series User's Manual (REJ10B0060)		
		Show below					

The HI7700/4 is updated in V.1.03 Release 01.

The target product is shown as follows.

Part No.	Version
R0R40770TRW011, R0R40770TRW015, R0R40770TRW01A, R0R40770TRW01K, R0R40770TRW01U, R0R40770TRW01Z, R0R40770TXW011, R0R40770TXW015, R0R40770TXW01A, R0R40770TXW01K, R0R40770TXW01U, R0R40770TXW01Z, HS0770ITI41SRE, HS0770ITI41SRB, HS0770ITI41SRS, HS0770ITI41SRE-E, HS0770ITI41SRB-E, HS0770ITI41SRS-E	V1.2.00 V1.3.00

Please download the update program from the following URL:

   http://download.renesas.com/eng/mpumcu/upgrades/os/index.html

[Contents of updates]

The following problem which had been reported by RENESAS TECHNICAL UPDATE TN-OS*-A084A/E have been fixed.

Note, this problem is actualized only in V1.2.00 and V1.3.00.

  [Phenomenon]

   In the system with optimized timer driver, if overrun handler function is used, the kernel may not carry out

   normal operation.

RENESAS