To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

RENESAS

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

DATE	21 February 2002		No.	TN-EML-080A/E
THEME	Version update for H8/3052 E6000 HDI due to the correction of a bug of the I/O port function when emulating mode 6 of the H8/3039 series			
CLASSIFICATION	☐ Spec change ☑ Limitation on Use ☐ Supplement of Documents			
PRODUCT NAME	H8/3052 E6000 emulator: HS3052EPI61H		Lot No.etc.	All lots of V1.10 or before
REFERENCE DOCUMENTS		Rev.	EffectiveDate	Permanent
			From	

In the H8/3052 E6000 Emulator HDI[1] System (system software) for H8/3052 E6000 (HS3052EPI61H), when mode 6 of the H8/3039 series is emulated, a bug that I/O port 1, 2, 3, or 5 illegally operates was corrected.

The HDI version after this correction is H8/3052 E6000 Emulator HDI System V1.12.

To correct this bug, the version of the HDI needs to be updated.
The program for updating version of the E6000 HDI will be shown in Hitachi's internet homepage.
Download the setup files[2] for H8/3052 E6000 Emulator HDI System V1.12 for use.

The URL address is as follows:
   http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download/e6k.html
If you do not have an internet environment, contact the sales agent. We will provide the setup program by the CD-R.

Notes: *1. HDI: Hitachi Debugging Interface
        *2. The program for updating version of the E6000 HDI will be uploaded on March 1st, 2002.