RENESAS Tool News

RENESAS TOOL NEWS on May 16, 2004: RSO-M3T-NC308WA-040516D

A Note on Using C-Compiler Packages M3T-NC308WA and M3T-NC30WA --On Debug Information--

Please take note of the following problem in using the M3T-NC308WA and M3T-NC30WA C-compiler packages (with assembler and integrated development environment):

- On debug information

---

1. **Products and Versions Concerned**
   M3T-NC308WA V.1.00 Release 1 through V.5.20 Release 1
   for the M32C/80, and M16C/80 series MCUs
   M3T-NC30WA V.1.00 Release 1 through V.5.30 Release 1
   for the M16C/60, M16C/30, M16C/Tiny, M16C/20, M16C/10, and R8C/Tiny series MCUs

2. **Description**
   Breakpoints may not be set in the functions defined within the files included by the #include preprocess command.

3. **Workaround**
   Define functions in a C source file.

4. **Schedule of Fixing the Problem**
   We plan to fix this problem in our next release of the products.

[Disclaimer]
The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.