[Notes]

E10A-USB Emulators

HS0005KCU01H and HS0005KCU02H

Outline

When using the E10A-USB emulators HS0005KCU01H and HS0005KCU02H, note the following point.

1. When the E10A-USB emulators are used for the H8S/2426, 2426R, and 2424 groups and the H8S/2456, 2456R, and 2454 groups, the function of the BREQ-B# pin is disabled.

1. When the E10A-USB Emulators are Used for the H8S/2426, 2426R, and 2424 Groups and the H8S/2456, 2456R, and 2454 Groups, the Function of the BREQ-B# Pin is Disabled.

1.1 Applicable Products

➢ E10A-USB emulators HS0005KCU01H and HS0005KCU02H

1.2 Applicable MCUs

➢ H8S family

H8S/2426, 2426R, 2424 groups

H8S/2456, 2456R, 2454 groups

1.3 Details

When the E10A-USB emulators are used for the H8S/2426, 2426R, and 2424 groups and the H8S/2456, 2456R, and 2454 groups, the function of the BREQ-B# pin is disabled.

Therefore, function of the BACK-B pin and BREQ0-B pin is also disabled.

1.4 Workaround

There is currently no workaround for this problem.

1.5 Schedule for Fixing the Problem

We do not plan to fix the problem.

RENESAS

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Sep. 1, 2017	-	First edition issued