RENESAS Tool News

Release Note of Real-Time OS RI78V4 V1.00.01 for 78K0R MCUs, RL78 Family Revised to Rev. 1.04

We have revised the release note of real-time OS RI78V4 V1.00.01 for the 78K0R MCUs, RL78 family from Rev. 1.03 to Rev. 1.04.

1. Release Notes to Be Updated

Title: RL78,78K0R Real-time OS RI78V4 V1.00.01 Release Note
Rev. Nos.: 1.00--1.03
Doc. Nos.: R20UT0638EJ0100, R20UT0638EJ0101, R20UT0638EJ0102, and
       R20UT0638EJ0103

2. Description

To Section 9.3, "Cautions for System Performance Analyzer AZ78K0R," the following items, which are relevant to the use of point trace, has been added:
  9.3.5, About user's point trace setup and setup of point trace of AZ
  9.3.6, About overflow of point trace

For further information, see Release Note Rev. 1.04 (Document No. R20UT0638EJ0104), which can be downloaded from here.