RENESAS Tool News

Code Generator for RL78 Family, 78K0R, and 78K0 MCUs Managed by CubeSuite+ Revised to V2.01.00

We have revised the code generator for the RL78 family, 78K0R, and 78K0 MCUs, CubeSuite+ Code_Generator for RL78_78K, from V2.00.01 to V2.01.00.

1. Products to Be Updated
   CubeSuite+ Code_Generator for RL78_78K V2.00.00 and V2.00.01

2. Descriptions of Revision
   (1) RL78/I1A Group of MCUs Supported Again
   The code generator for the RL78/I1A group of MCUs was taken out of
   the support line temporarily in the CubeSuite+ Code_Generator
   for RL78_78K V2.00.01 released on September 30, 2013.
   Note that it has again been added to the support line in the newest
   version.

   (2) Device Support
   The following MCUs have been added to the support line:
     - RL78/F13, RL78/F14, and RL78/G1C groups of MCUs (RL78 family)

   You can also see this description at:

   https://www.renesas.com/cubesuite+/CubeSuitePlus_Code_Generator_for_RL78_78K.html

   This page will be updated on November 20.

3. Updating Your Product
   Online updating is available free of charge. To update either your
   commercial edition or evaluation edition of CubeSuite+, use either of
   the following methods.

   If you are using the common program group of CubeSuite+ V1.03.00 or
   earlier, please download and install the evaluation edition of

CubeSuite+ V2.01.00 from the following URL:
  https://www.renesas.com/cs+_download
The above URL is one of our global sites.

 (1) Use Update Manager
    On the Start menu, select Programs and then Renesas
    Electronics CubeSuite+ to start the Update Manager.
    This service will be available on and after November 18.

    Note: If your CubeSuite+ has been launched with the
        rapid startup enabled, exit the CubeSuite+ once,
        and then run the Update Manager.
        If the CubeSuite+ is resident in the notification area
        of Windows (system tray) due to rapid startup,
        an error occurs with the following message:

        M0120001
        Installation is suspended because "CubeSuite+W.exe" is
        running.
        It will be resumed next time you start the tool.
        ----

 (2) Download the installer of the product from our Web site

    Download CubeSuite+ Code_Generator for RL78_78K V2.01.00
    from the following URL:
      https://www.renesas.com/cs+_download
    Then install it.
    The above program will be published on November 20.
    The above URL is one of our global sites.