RENESAS Tool News

The Emulator Software for the E10A-USB Emulator Revised to V.1.11 Release 00

We have revised the emulator software for the E10A-USB emulator to V.1.11 Release 00. (The emulator emulates the SuperH RISC engine family; the H8S and H8SX families of MCUs and MPUs.)

1. **Emulator Concerned**
   E10A-USB
   (Product types: HS0005KCU01H and HS0005KCU02H)

2. **Descriptions of Revision**

   (1) The H8SX device group supported. They are as follows:
   H8SX/1527F, H8SX/1525F, and H8SX/1582F

   (2) The SH7619 MPU added to the supported line of the SH-2 device group.

   (3) The SH7325 and SH7341 MPUs added to the supported line of the SH-Mobile device group.

   The devices listed in items (2) and (3) have already been supported since the release of the emulator software V.1.10 Release 00 (its download site was opened on February 21, 2005). We are sorry that we have not informed you of it.

3. **How to Revise Your Product**

   (1) If you have not already installed the emulator software, execute the Setup.exe file in the CD-ROM included with the product to install it.

   (2) Download the latest version of the High-performance Embedded Workshop to update yours from the Software Download Site.

(3) Download the update program of the emulator software for the E10A-USB emulator V.1.11 Release 00 device by device from the Software Download Site (available on and after this March 23).

(4) Execute the downloaded update program (an executable file).

(5) Execute the setup tool for the E10A-USB emulator to complete the setup of the emulator software for the emulator.

NOTICE:
The above-mentioned update program cannot switch the device group you are using to another one.