RENESAS Tool News

Free-of-Charge Evaluation Edition of Renesas Flash Programmer
Revised to V1.03.00

We have revised the free-of-charge evaluation edition of Renesas Flash Programmer, a flash ROM programming software tool, from V1.02.00 to V1.03.00.
For an overview of the product, visit the Web site at:
  http://www.renesas.com/rfp
The above URL is one of our global sites.

1. Descriptions of Revision

1.1 Device Support
The following MCUs have been added to the support line:
(1) In RL78 family
   - R5F104AA, R5F104AC, R5F104AD, R5F104CA, R5F104CC, R5F104CD,
     R5F104EA, R5F104EC, R5F104ED, R5F104FA, R5F104FC, R5F104FD,
     R5F104GA, R5F104GC, R5F104GD, R5F104JC, R5F104JD, R5F104LC,
     R5F104LD, R5F104MJ, and R5F104PJ (RL78/G14 group)
   - R5F10266, R5F10267, R5F10268, R5F10269, R5F1026A, R5F10277,
     R5F10278, R5F10279, R5F1027A, R5F102A7, R5F102A8, R5F102A9,
     R5F102AA, R5F10366, R5F10367, R5F10368, R5F10369, R5F1036A,
     R5F10377, R5F10378, R5F10379, R5F1037A, R5F103A7, R5F103A8,
     R5F103A9, and R5F103AA (RL78/G12 group)
   - R5F10E8A, R5F10E8C, R5F10E8D, R5F10E8E, R5F10EBA, R5F10EBC,
     R5F10EBD, R5F10EBE, R5F10EGA, R5F10EGC, R5F10EGD, R5F10EGE,
     R5F10ELC, R5F10ELD, and R5F10ELE (RL78/G1A group)

   (2) In V850
   - UPD70F3474B, UPD70F3475B, UPD70F3476B, UPD70F3477B,
     UPD70F3478B, UPD70F3479B, UPD70F3931B, UPD70F3932B,
     UPD70F3933B, UPD70F3934B, UPD70F3935B, UPD70F3936B,
     UPD70F3937B, UPD70F3938B, and UPD70F3939B (V850E/SJ3-H)
   - UPD70F3480B, UPD70F3481B, UPD70F3482B, UPD70F3486B,

UPD70F3487B, UPD70F3488B, UPD70F3925B, UPD70F3926B, and
UPD70F3927B (V850E/SK3-H)
- UPD70F3505A (V850E2/PG4)
- UPD70F3507M2 (V850E2/PJ4)
- UPD70F4009 (V850E2/FK4)
- UPD70F4012 (V850E2/FL4)
- UPD70F3543 (V850E2/FF4-M)

(3) In RX family
- R5F5630E and R5F5630D (RX630 group)
- R5F562TAE, R5F562TAD, R5F562TAB, R5F562TAA, R5F562T7E,
R5F562T7D, R5F562T7B, R5F562T7A, R5F562T6E, R5F562T6D,
R5F562T6B, and R5F562T6A (RX62T group)
- R5F562N8 and R5F562N7 (RX62N group)
- R5F56218, R5F56217, and R5F56216 (RX621 group)
- R5F56108, R5F56107, R5F56106, and R5F56104 (RX610 group)
- R5F52108A, R5F52107A, R5F52106A, and R5F52105A (RX210 group)

1.2 Support for Revised MCU
The UPD70F4006 MCU (V850E2/FJ4 group) has been revised to device version
1.1. According to this revision, the programmer supports this MCU.

1.3 Problem Fixed
The following known problem has been fixed:
- With programming flash ROMs of V850ES/Jx3 and V850ES/Sx3 MCUs
For details, see RENESAS TOOL NEWS Document No. 111201/tn3 on
the Web page at:
http://tool-support.renesas.com/eng/toolnews/111201/tn3.htm

2. Obtaining the Revised Product

Download the installer of the product from the Web site at:
http://www.renesas.com/rfp_download
This site will be opened on this December 26.
The above URL is one of our global sites.