RENESAS Tool News

H8S/Tiny E100 Emulator Software Revised and Renamed

We have revised H8S/Tiny E100 Emulator Software from V.1.00 Release 00 to V.2.00 Release 00 and renamed the product to H8S/Tiny H8S/2400 E100 Emulator Software at the same time. For an overview of the product, go to https://www.renesas.com/e100 and click "Debug Functions" on the "E100" menu at the upper left of the page.
The above URL is one of our global sites.

1. Product to Be Updated

H8S/Tiny E100 Emulator Software V.1.00 Release 00
This emulator software is bundled with the R0E420000MCU00 MCU unit.

2. Descriptions of Revision

2.1 Supported MCUs Increased

The following MCUs of the H8S/2427, /2427R, and /2425 groups (H8S/2400 series) have been added to the support line:
R4F24255, R4F24256, R4F24258, R4F24259, R4F24275, R4F24276, R4F24278, R4F24279, R4F24275R, R4F24276R, R4F24278R, and R4F24279R

NOTE: To debug your systems, you need to use a optional MCU unit R0E424270MCU00.

2.2 Problem Fixed

The following known problem has been fixed:
- The user program breaks at indefinite places other than breakpoints.
For details, see RENESAS TOOL NEWS Document No. 100616/tn5 at:
https://www.renesas.com/search/keyword-search.html#genre=document&q=100616tn5

3. How to Update Your Product

Online update is available free of charge. Update yours in either of the following ways:

(1) Use AutoUpdate Utility. This service is available on and after
   August 5.
(2) Download the update program of the revised product from:
   https://www.renesas.com/e100_download
   Then execute it. This site will be opened from August 5 on.
   The above URL is one of our global sites.

   NOTICE:
   If the above update program is executed in the system where
   High-performance Embedded Workshop V.4.07.00 or earlier resides,
   it will be upgraded to V.4.07.01.