RENESAS Tool News

RENESAS TOOL NEWS on April 16, 2015: 150416/tn6

Revision and Change to the Name of the Application Leading Tool for RL78

Application Leading Tool for RL78: from V1.05.00 to V1.06.00
The name will be changed from "Application Leading Tool for RL78" to "AP4 for RL78".

---

1. Description of Revision
   Revised from V1.05.00 to V1.06.00
   The following revisions will be made in V1.06.00.

   (a) The problem on the following point announced in a cautionary note
   (issue No. 140816/tn4 of Renesas Tool News) will be fixed.

   With setting of P20 and P21 of port 2 (target: RL78/L1C group)

   For more information on the problem, refer to the URL below.
   https://www.renesas.com/search/keyword-search.html#genre=document&q=140816tn4

   (b) The problem on the following point announced in cautionary note 3
   (issue No. 141216/tn5 of Renesas Tool News) will be fixed.

   3. Saving Projects with Settings for the A/D Convertor
   Applicable Products: RL78/L1C Group
   For that issue of Tool News, giving more information on the problem, refer to the URL below.
   https://www.renesas.com/search/keyword-search.html#genre=document&q=141216tn5
2. Obtaining the Product
   Download the installer from the URL below to install the program.
   The program will be available from April 20.
   https://www.renesas.com/applilet_download

[Disclaimer]
The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.