RENESAS Tool News

RL78 Code Generator for CS+ (CS+ for CA, CX) Revised

We are revising the RL78 code generator for CS+ (CS+ for CA, CX) from V2.07.00 to V2.08.00.

1. Products Concerned
   V2.07.00 of the RL78 code generator for CS+ (CS+ for CA and CX).
   (CS+ for CA, CX Code_Generator for RL78)

2. Descriptions of Revision
   (a) Addition of supported MCUs
       The following group has been added to the set of supported MCUs.
       RL78 family: RL78/G1F group

   (b) Modification of defect
       The previous version output incorrect values to the option byte
       LVIMDS1 (used to set the interrupt mode of the power detection
       circuit), so we have modified the code to output correct values.
       Change your product to version V2.08.00 if you are using the code
       generator and any of the target MCUs. Refer to the release note which
       is installed along with the product for details.

       Target MCU
       RL78 family: RL78/F13, RL78/F14, RL78/L12, and RL78/G1A groups

3. Updating Your Product
   Online updating is available free of charge.
   To update either your commercial edition or evaluation edition of CS+,
   use either of the following methods.

   If your product is CS+ V3.00.00 or an earlier version, you will need to
   update your CS+ to V 3.00.01 in advance.
   Download and install the evaluation edition of CS+ V3.01.00 from the
   following URL:
   https://www.renesas.com/cs+_download

(1) Use the Update Manager
    On the "Start" menu, select "Programs" and then "Renesas Electronics
    CS+" to start the Update Manager. This service will be available on
    and after June 22.

    Note: If your CS+ has been launched with rapid startup enabled,
          exit the CS+ once, and then run the Update Manager.
          If the CS+ is resident in the notification area of Windows
          (system tray) due to rapid startup, attempting to run the
          Update Manager produces an error and the following message.

          M0120001
          Installation is suspended because "CS+W.exe" is running.
          It will be resumed next time you start the tool.
          ----

(2) Download the installer of the product from our Web site
    Download "CS+ for CA, CX Code_Generator for RL78 V2.08.00" from the
    URL below to install the program.
    The program will be available from June 22.
    https://www.renesas.com/cs+_download