

[Notes] Solution Toolkit QE for Capacitive Touch Development Assistance Tool for Capacitive Touch Sensors

R20TS0785EJ0100
Rev.1.00
Dec.16.21

Outline

When using of the products in the title, note the following points.

- Notes on using tuning processing with advanced settings on CTSU.

1. Notes on using tuning processing with advanced settings on CTSU

1.1 Applicable Products

Development Assistance Tool for Capacitive Touch Sensors

- QE for Capacitive Touch[RA] V1.2.0
- QE for Capacitive Touch[RA,RL78] V1.3.0
- QE for Capacitive Touch[RA,RL78,Synergy] V1.4.0
- QE for Capacitive Touch[RA,RL78,Synergy] V1.4.1
- QE for Capacitive Touch V2.0.0

1.2 Applicable Devices

RX Family: RX113, RX130, RX230, RX231, RX23W, RX671

RA Family: RA2A1, RA4M1, RA4M2, RA4M3, RA4W1, RA6M1, RA6M2, RA6M3, RA6M4, RA6M5


Renesas Synergy: S124, S128, S1JA, S3A1, S3A3, S3A6, S3A7, S5D3, S5D5, S5D9, S7G2

1.3 Details

The value set in the "Measurement Frequency" field will not be applied, resulting in an incorrect adjustment result.

1.4 Conditions

It occurs when tuning processing with advanced settings is used for the corresponding device and a value other than "Auto" is selected in the "Measurement Frequency" field.



1.5 Workaround

There is no workaround. Please contact us.

- <https://www.renesas.com/contact/>

1.6 Schedule for Fixing the Problem

This problem will be fixed in the next version. (Scheduled to be released in December 2021.)

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Dec.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,
Koto-ku, Tokyo 135-0061, Japan
www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:
www.renesas.com/contact/