

RENESAS TOOL NEWS on October 12, 2007: 071012/tn1

Flash Development Toolkit Revised to V.4.00 Release 02

We have revised Flash Development Toolkit from V.4.00 Release 01 to V.4.00 Release 02. The tool kit is used for the SuperH RISC engine, M16C, H8SX, H8S, H8, and 740 families of MCUs.

1. Descriptions of Revision

1.1 Supported MCUs Increased

The following MCUs have been added to the support line; they are programmable via the E8a on-chip debugging emulator, the HS0008EAUF1H adaptor board for on-board programming, or the RS-232C port:

(1)E8a Emulator, HS0008EAUF1H, or RS-232C Usable for Programming

H8S family:	H8S/2280BF, H8S/2280RBF, H8S/2602F, H8S/2604F, H8S/2607F, H8S/2609F
H8 family:	H8/38002F

(2)E8a Emulator Usable for Programming

The E8a emulator can be used for programming the following MCUs as well as the HS0008EAUF1H and the RS-232C:

H8S	H8S/2612F,
family:	H8S/2628F,
	H8S/2630F,
	H8S/2635F,

	H8S/2649F
H8	H8/38014F,
family:	H8/38124F

(3)RS-232C Usable for Programming

The RS-232C port can be used for programming the following MCUs in the M16C family as well as the E8 and the E8a:

```
M30882FW, M30882FJ,
M30882FH, M30880FW,
M30880FJ, M30880FH,
M3087BFL, M3087BFK,
M30879FL, M30879FK,
M30878FJ, M30876FJ,
M30875FH, M30873FH,
M30865FJ, M30855FW,
M30855FJ, M30855FH,
M30853FW, M30853FJ,
M30853FH, M30852FJ,
M30850FJ, M30845FW,
M30843FW, M30843FJ, and
M30843FH
```

1.2 Problem Fixed with Programming QzROM-version MCUs in the 740 Family

The problem with programming the internal ROM of QzROM-version MCUs in the 740 family has been fixed.

For details, see RENESAS TOOL NEWS Document No. 070916/tn5, published on September 16, 2007, at

http://tool-support.renesas.com/eng/toolnews/070916/tn5.htm

2. How to Update Your Product

Free-of-charge online update is available.

Download the installer of the latest program from the Web site at http://www.renesas.com/fdt_download

and execute it. This site will be opened on and after October 17.

Also you are able to update yours from V.4.00 Release 01 to its Release 02 using AutoUpdate Utility.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

 $\ @$ 2010-2016 Renesas Electronics Corporation. All rights reserved.