

Product Advisory (PA)

Subject: Correction of Manufacturing Part Number (MPN) Product Label to remove Pb-free

designation symbol

Publication Date: 11/14/2023 Effective Date: 11/14/2023

Revision Description:

Initial Release

Description of Change:

This notice is to inform you that Renesas Electronics America Inc will remove Pb-free designation symbol from the product label. The associated datasheet will be updated accordingly.

As of the effective date of the PCN, Renesas Electronics America, Inc. will start to fulfill orders using the new product label (without Pb-free designation symbols). Please refer to Appendix B for details of the label change.

While, customer may expect to receive shipments with existing label (Pb-free logo) on the inner boxes or labels after the effective date, until such time the inventories have been fully depleted.

In parallel to label change (remove Pb-free designation symbols), the associated datasheet will be updated accordingly.

There is no change to the new Renesas integrated interior label as announced via PA220009 to which schedule to release by Year 2024 Quarter 3.

Please contact your local sales representative for more information of the change.

Reason for Change:

The correction to the MPN label aligns the product RoHS classification.

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

Product Identification:

Product affected by this change is identifiable via Renesas's internal traceability system.

Qualification status: Not Applicable **Sample availability:** Not Available

Device material declaration: Available upon request



Note:

- 1. Acknowledgement must be received by Renesas within 30 days or Renesas will consider the change as approved.
- 2. If timely acknowledgement is provided by Customer, then Customer shall have 90 days from the date of receipt of this PCN to make any objections to this PCN. If Customer fails to make objections to this PCN within 90 days of the receipt of the PCN then Renesas will consider the PCN changes as approved.
- 3. If customer cannot accept the PCN then customer must provide Renesas with a last time buy demand and purchase order.

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)				
Americas: PCN-US@RENESAS.COM	Europe: PCN-EU@RENESAS.COM	Japan: PCN-JP@RENESAS.COM	Asia Pac: PCN-APAC@RENESAS.COM	

Appendix A : Affected Product List

ISL99227IRZ-TR5796	ISL99390HRZ-TR5935	RAA2214904GNP#HB0
ISL99360BFRZ-T	ISL99392FRZ-TR5935	RAA2214904GNP#HBA
ISL99360FRZ-T	RAA220075RGNP#HB0	RAA2214904GNP#HBB
ISL99360FRZ-TS2696	RAA220075RS0BGNP#HB0	RAA2214904S04GNP#HB0
ISL99360FRZ-TS2795	RAA2201054GNP#HB0	RAA2214904S04GNP#HBA
ISL99360HRZ-T	RAA2201054GNP#HB1	RAA2214904S05GNP#HB0
ISL99360HRZ-TS2709	RAA2209004GNP#HB0	RAA2214904S05GNP#HBA
ISL99380BFRZ-TR5935	RAA2213204GNP#HB0	RAA2214904S0DGNP#HB0
ISL99380FRZ-TR5935	RAA2213204S02GNP#HB0	RAA2214904S0DGNP#HBA
ISL99380FRZ-TR5953	RAA2213204S05GNP#HB0	RAA2214904S0EGNP#HB0
ISL99380FRZ-TS2773	RAA221320RGNP#HB0	RAA2214904S0EGNP#HBA
ISL99380HRZ-TR5935	RAA2213404GNP#HB0	RAA2214914GNP#HB0
ISL99390BFRZ-TR5935	RAA2213404R1YGNP#HB0	RAA2214914S02GNP#HB0
ISL99390FRZ-TR5935	RAA2213404S02GNP#HB0	RAA2214914S06GNP#HB0
ISL99390FRZ-TR5948	RAA2213404S05GNP#HB0	RAA2214914S0DGNP#HB0
ISL99390FRZ-TR5953	RAA221340RGNP#HB0	RAA2214944GNP#HB0
ISL99390FRZ-TS2773	RAA2213504GNP#HB0	RAA2214964GNP#HB0
	ISL99360BFRZ-T ISL99360FRZ-T ISL99360FRZ-TS2696 ISL99360FRZ-TS2795 ISL99360HRZ-T ISL99360HRZ-T ISL99360HRZ-TS2709 ISL99380BFRZ-TR5935 ISL99380FRZ-TR5935 ISL99380FRZ-TR5953 ISL99380FRZ-TR5935 ISL99380HRZ-TR5935 ISL99390BFRZ-TR5935 ISL99390FRZ-TR5935 ISL99390FRZ-TR5935	ISL99360BFRZ-T ISL99392FRZ-TR5935 ISL99360FRZ-T RAA220075RGNP#HB0 ISL99360FRZ-TS2696 RAA220075RS0BGNP#HB0 ISL99360FRZ-TS2795 RAA2201054GNP#HB0 ISL99360HRZ-T RAA2201054GNP#HB1 ISL99360HRZ-TS2709 RAA2209004GNP#HB0 ISL99380FRZ-TR5935 RAA2213204GNP#HB0 ISL99380FRZ-TR5935 RAA2213204S02GNP#HB0 ISL99380FRZ-TR5953 RAA2213204S05GNP#HB0 ISL99380FRZ-TS2773 RAA221320RGNP#HB0 ISL99390BFRZ-TR5935 RAA2213404GNP#HB0 ISL99390FRZ-TR5935 RAA2213404R1YGNP#HB0 ISL99390FRZ-TR5948 RAA2213404S05GNP#HB0 ISL99390FRZ-TR5953 RAA2213404S05GNP#HB0 ISL99390FRZ-TR5953 RAA2213404S05GNP#HB0



Appendix B: Remove Pb-Free designation symbol

