



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: **L-04-01R1**

Last Buy Date: April 26, 2005

Issue Date: April 26, 2004

Last Ship Date: July 26, 2005
(3 months after last buy date)

PRODUCT(S) AFFECTED:

(List Replacement Part #(s), if any)

ATTACHMENT

☒ Yes ☐ No

See attached list.

Revision "R1": Revised last buy date and last ship date on select products, marked with "***".

Please see attachment for details.

REASON FOR DISCONTINUANCE:

☐ Replace slower speed with faster speed offerings

☐ Other:

☐ Obsolete Fab Technology / Process

☐ Obsolete Assembly Technology / Process

☐ Obsolete Package / Material

☒ Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax#: _____

CUSTOMER COMMENTS:

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN# L-04-01R1 Attachment

| Affected IDT Part # | Replacement Part # |
|---------------------|--------------------|
| IDT54FCT821ALB | No Replacement |
| IDT54FCT821BLB | No Replacement |
| IDT54FCT821ADB | No Replacement |
| IDT54FCT821BDB | No Replacement |
| IDT5962-88608013A | No Replacement |
| IDT5962-88608023A | No Replacement |
| IDT5962-8860801LA | No Replacement |
| IDT5962-8860802LA | No Replacement |
| IDT74ALVC244Q | No Replacement |
| IDT74ALVC244PG | No Replacement |
| IDT74ALVC244SO | No Replacement |
| IDT74ALVC244PY | No Replacement |
| IDT74ALVCH16244PF | No Replacement |
| IDT74FCT821ASO | No Replacement |
| IDT74FCT821BSO | No Replacement |
| IDT74FCT833ASO | No Replacement |
| IDT74FCT833BSO | No Replacement |
| ** IDT74LVC07ADC | No Replacement |
| ** IDT74LVC07APG | No Replacement |
| ** IDT74LVC07APY | No Replacement |
| IDT74LVC08ADC | No Replacement |
| IDT74LVC08APG | No Replacement |
| IDT74LVC08APY | No Replacement |
| IDT74LVC163APG | No Replacement |
| IDT74LVC373AQ | No Replacement |
| IDT74LVC373APG | No Replacement |
| IDT74LVC373ASO | No Replacement |
| IDT74LVC373APY | No Replacement |
| IDT74LVCH16652APA | No Replacement |
| IDT74LVCH16652APV | No Replacement |
| ** IDT74LVCR2245AQ | No Replacement |
| ** IDT74LVCR2245APG | No Replacement |
| ** IDT74LVCR2245ASO | No Replacement |
| ** IDT74LVCR2245APY | No Replacement |

Note: Due to declined inventory, IDT cannot support the last buy orders on select products marked with "**". Therefore, there is no last buy or ship date for these select products. These are multisourced devices, and are available from other commodity device manufacturers.