## PRODUCT ADVISORY

## Data Sheet Specification Change for Intersil Product ISL59885\*

Refer to: PA11110

Date: November 1, 2011

INTERSIL CORPORATION | 1650 Robert J. Conlan Blvd. | Palm Bay, FL USA 32905 | Telephone 321-724-7000 | www.intersil.com



November 1, 2011

## To: Our Valued Intersil Customers

## Subject: Data Sheet Specification Change for Intersil Product ISL59885\*

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL59885\* products. The change to  $\theta_{JA}$  for the SOIC (Small Outline Integrated Circuit) package in the Thermal Information section aligns the data sheet with the product characteristics. The updated data sheet is available on the Intersil web site at <a href="http://www.intersil.com/data/fn/fn7442.pdf">http://www.intersil.com/data/fn/fn7442.pdf</a>.

Products affected:

ISL59885ISZ ISL59885ISZ-T13 ISL59885ISZ-T7A ISL59885ISZ-T7A

Data sheet specification changes for  $\theta_{JA}$  are as follows:

Thermal Resistance	Current Value	New Value	Units
8p SOIC	110	120	°C/W

There will be no change in external marking of the packaged parts. There have been no changes made to the die/silicon or device itself.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,

on Brewster

Jon Brewster Intersil Corporation

PA11110

CC: J. Touvell J. Bailey K. Tucker