

Product Advisor (PA)

Subject: Corrections to Standard Microcircuit Drawing 5962-15220 for Intersil Product ISL71841* and ISL73841*

Publication Date: 9/26/2016

Effective Date: 9/26/2016

Revision Description:

Initial Release

Description of Change:

This advisory is to inform you that Intersil has made corrections to DLA (Defense Logistics Agency) Land and Maritime SMD (Standard Microcircuit Drawing) 5962-15220 for the ISL71841* and ISL73841* series products. The updates correct errors in the Terminal symbol for case outline X and Y as shown in Figure 2. For case outline X, pin 23 terminal symbol is now A2 and for case outline Y, pin 22 is now A2. There have been no changes to the die/silicon or product itself.

Products Affected:

Intersil Part Number	DLA SMD Part Number
ISL71841SEHVF	5962R1522001VXC
ISL71841SEHVL	5962R1522001VYA
ISL71841SEHVX	5962R1522001V9A
ISL73841SEHVF	5962L1522002VXC
ISL73841SEHVX	5962L1522002V9A

Reason for Change:

Standard Microcircuit Drawing correction to properly list Terminal symbols for case outline X and Y as shown in Figure 2 of the SMD. The SMD is available on the DLA website at: <https://landandmaritimeapps.dla.mil/Downloads/MilSpec/Smd/15220.pdf>

Impact on fit, form, function, quality & reliability:

The change will have no impact on the form, fit, function, quality, reliability and environmental compliance of the devices.

Product Identification:

Standard Microcircuit Drawing correction only, no change to the product.

Qualification status: Not applicable

Sample availability: 9/26/2016

Device material declaration: Available upon request

Questions or requests pertaining to this change notice, including additional data or samples, must be sent to Intersil within 30 days of the publication date.

For additional information regarding this notice, please contact your regional change coordinator (below)			
Americas: PCN-US@INTERSIL.COM	Europe: PCN-EU@INTERSIL.COM	Japan: PCN-JP@INTERSIL.COM	Asia Pac: PCN-APAC@INTERSIL.COM