## Old Company Name in Catalogs and Other Documents

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: http://www.renesas.com

April 1<sup>st</sup>, 2010 Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (http://www.renesas.com)

Send any inquiries to http://www.renesas.com/inquiry.

## **RENESAS TECHNICAL UPDATE**

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-EML-113A/EA	Rev.	1.0
Title	Correction of Errors in the H8S Family E10A Emulator Additional Document for User's Manual Specific Guide for the H8S/2218F E10A Emulator		Information Category	Correction or Supplement of Document		
Applicable Product	H8S/2218F E10A Emulator HS2218KCM01H HS2218KCI01H	Lot No.	Reference Document	H8S Family E10A Emulator Additional Document for User's Manual Specific Guide for the H8S/2218F E10A Emulator (REJ10B0018-0100H, Rev1.00)		
		V1.0.00				

Please note that there are errors in the H8S Family E10A Emulator Additional Document for User's Manual Specific Guide for the H8S/2218F E10A Emulator (REJ10B0018-0100H, Rev1.00), which must be corrected as listed below.

Descriptions:

Correction 1: Figure 1.2 in page 3, figure 1.3 in page 4, and figure 1.7 in page 7

(After change)

Pull up pin FWE. Due to a change of pin names for the H8S/2218F MCU, we have deleted the multiplexed names of the five pins.




Figure 1.2 Pin Assignments of the H-UDI Port Connector



