

To our customers,

---

## Old Company Name in Catalogs and Other Documents

---

On April 1<sup>st</sup>, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1<sup>st</sup>, 2010  
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

(Note)

URL described on the body is not active. Please refer to following URL.

[http://www.renesas.com/fmwk.jsp?cnt=/download\\_search\\_results.jsp&fp=/support/downloads/download\\_results&layerId=1184](http://www.renesas.com/fmwk.jsp?cnt=/download_search_results.jsp&fp=/support/downloads/download_results&layerId=1184)

date: 2002/04/26

## HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Tools			No	TN-EML-084A/E	
THEME	Emulation on SCI0 when Using the H8/3048F-ONE E10T Emulator		Classification of Information	1. Spec change 2. Supplement of Documents 3. Limitation of Use	4. Change of Mask 5. Change of Production Line	
PRODUCT NAME	HS3048BTCM01H or HS3048BTCI01H	Lot No.	Reference Documents	H8/3048F-ONE E10T Emulator User's Manual Rev. 1.0 (ADE-702-287)	Rev.	Effective Date
		All lots			1.0	Permanent

We will inform that the following malfunction was found in Hitachi's H8/3048F-ONE E10T emulator.

When the H8/3048F-ONE E10T emulator is used, the SCI0 channel of the H8/3048F-ONE and the I/O port functions for P90, P92, and P94 cannot be used.

We are making software for correcting this malfunction. For the release of this software, we will upload the difference file on the web site from May 2002.

Web Address:

<http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download/e10t.html>