Date: Aug. 8, 2019

RENESAS TECHNICAL UPDATE

TOYOSU FORESIA, 3-2-24, Toyosu, Koto-ku, Tokyo 135-0061, Japan Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RX*-A0213A/E	Rev.	1.00
Title	Errata to the Package Code of 0.65-mm pitch 80-pin LQFP Package for RX66T Group and RX24T Group		Information Category	Technical Notification		
Applicable Product	RX66T Group, RX24T Group	Lot No.	Reference Document	RX66T Group User's Manual: Hardware		
		All		Rev.1.10 (R01UH0749EJ0110) RX24T Group User's Manual: Hardware Rev.2.00 (R01UH0576EJ0200)		

This document describes a correction to the package code (RENESAS Code) of the 0.65-mm pitch 80-pin LQFP package in the User's Manual: Hardware for the applicable products stated above. Changes in the package dimensions that accompany this correction are also made.

1. Correction to the Package Code (RENESAS Code)

The package code of the 0.65-mm pitch 80-pin LQFP package used with the applicable products is corrected as follows.

Before correction

PLQP0080JA-A

After correction


PLQP0080JA-B

2. Changes in Package Dimensions

The package dimensions for the 0.65-mm pitch 80-pin LQFP package are also changed as shown in the following figures.



Before correction



After correction

