

To our customers,

Old Company Name in Catalogs and Other Documents

On April 1st, 2010, NEC Electronics Corporation merged with Renesas Technology Corporation, and Renesas Electronics Corporation took over all the business of both companies. Therefore, although the old company name remains in this document, it is a valid Renesas Electronics document. We appreciate your understanding.

Renesas Electronics website: <http://www.renesas.com>

April 1st, 2010
Renesas Electronics Corporation

Issued by: Renesas Electronics Corporation (<http://www.renesas.com>)

Send any inquiries to <http://www.renesas.com/inquiry>.

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment		No	TN-EML-106A/E	Rev	1
THEME	Problems with the SH7294 and the SH7300 Series E10A Emulators	Classification of Information		1. Spec change 2. Supplement of Documents ③ Limitation of Use 4. Change of Mask 5. Change of Production Line		
PRODUCT NAME	SH7294 E10A Emulator SH7300 Series E10A Emulator	Lot No.	Reference Documents	SH7294 E10A Emulator User's Manual Rev1.0		Effective Date
		V1.00		ADE-702-346 SH7300Series E10A Emulator User's Manual Rev1.0 ADE-702-363		Eternity

We have found that SH7294 and SH7300 Series E10A emulators have the following problems:

When the CCR register is written to from the I/O window, 'Verify error' is displayed even if the register has been written to correctly.

Note that the operation is performed normally although these messages are incorrect.
These problems are to be corrected in V2.0.00.