# **Microcomputer Technical Information**

CP(K), O

|                                  |                           | Document No.   | ZBG-  | -CD-05-0101           | 1/3 |
|----------------------------------|---------------------------|----------------|---|-----------------------|-----|
| QB-78K0LX2                       |                           | Date issued    | November 8, 2005                            |                       |     |
| In-Circuit Emulator for          |                           | Issued by      | Development Tool Group                      |                       |     |
| 78K0/LE2, 78K0/LF2, 78K0/LG2     |                           |                | Multipurpose Microcomputer Systems Division |                       |     |
|                                  |                           |                | 4th Systems Operations Unit                 |                       |     |
| Replacement of Exchange Adapters |                           |                | NEC Electronics Corporation                 |                       |     |
| Related                          | QB-78K0LX2 User's Manual: | Notification   |   | Usage restriction     |     |
| documents                        | U17468EJ2V0UM00           | classification |   | Upgrade               |     |
|                                  |                           |                |   | Document modification |     |
|                                  |                           |                | V   | Other notification    |     |

#### 1. Affected products

The exchange adapters included with the following in-circuit emulators that were shipped by the end of October 2005 are affected.

- QB-78K0LX2-T80GK04
- QB-78K0LX2-T80GK05
- QB-78K0LX2-T80GC04
- QB-78K0LX2-T80GC05
- QB-78K0LX2-T64GB
- QB-78K0LX2-T64GK

The following exchange adapters that were shipped by the end of October 2005 are affected.

- QB-80GK-EA-04T
- QB-80GK-EA-05T
- QB-80GC-EA-04T
- QB-80GC-EA-05T
- QB-64GB-EA-07T
- QB-64GK-EA-05T

## 2. Details of fault

#### [Description]

A faulty wiring exists in the portion related to the segment signal (Sx) in the exchange adapter. Due to this faulty wiring, the segment signal (Sx) that should be output from the target device is output from pins different from the correct device pins.

Sx: 80-pin products (with A/D): S0 to S25 80-pin products (without A/D): S0 to S35

64-pin products: S0 to S19

## [Workaround]

When performing debugging with the in-circuit emulator, clear bit 6 (SEGSET1) and bit 7 (SEGSET2) of the LCD mode select register (LCDMD) to "0".

When writing to the actual device, change the values of the LCDMD register according to the settings in each device.

#### 3. Modification schedule

The improved exchange adapters will be manufactured according to the following schedule.

QB-80GK-EA-04T: Late November 2005 QB-80GK-EA-05T: Late November 2005 QB-80GC-EA-04T: Early December 2005 QB-80GC-EA-05T: Early December 2005 QB-64GB-EA-07T: Mid-December 2005 QB-64GK-EA-05T: Mid-December 2005

#### 4. Notification


We will send the improved exchange adapter to customers who have already purchased an affected product for development with the 78K0/LF2 or 78K0/LF2.

Applications for sending the exchange adapter will be accepted according to the following schedule, so contact an NEC Electronics sales representative or distributor. (Please wait about two weeks for delivery.)

QB-80GK-EA-04T: November 16, 2005 QB-80GK-EA-05T: November 20, 2005 QB-80GC-EA-04T: November 24, 2005 QB-80GC-EA-05T: November 28, 2005 QB-64GB-EA-07T: December 2, 2005 QB-64GK-EA-05T: December 6, 2005

\* Note that this schedule is subject to change without notice. For the detailed release schedule of modified products, contact an NEC Electronics sales representative.

On the improved exchange adapters, a white dot mark is appended at the lower-right corner of the NEC logo.



| ZBG-CD-05-0101 | 3/3 |
|----------------|-----|
|                | 0.0 |

## 5. Document revision history

# QB-78K0LX2 In-Circuit Emulator for 78K0/LE2, 78K0/LF2, 78K0/LG2 Replacement of Exchange Adapters

| Document Number | Issued on        | Description    |
|-----------------|------------------|----------------|
| ZBG-CD-05-0101  | November 8, 2005 | Newly created. |