Date: August 26, 2010

RENESAS TECHNICAL UPDATE

1753, Shimonumabe, Nakahara-ku, Kawasaki-shi, Kanagawa 211-8668 Japan Renesas Electronics Corporation

Product Category	MPU/MCU		Document No.	TN-RX*-A004A/E	Rev.	1.00
Title	RX610 Group Error Correction of the table List of Pins and Pin Functions (176-Pin LFBGA)		Information Category	Technical Notification		
Applicable Product	RX610 Group	Lot No.				
		All lots	Reference Document	RX610 Group Hardware Manual		

Thank you for your consistent patronage of Renesas semiconductor products.

We would like you to inform you of error correction of the table List of Pins and Pin Functions (176-Pin LFBGA) in the RX610 group.

Table 1.3 List of Pins and Pin Functions (176-Pin LFBGA)

	Pin No.	Power Supply
	176-Pin	Clock
	LFBGA	System Control
Before Change	P11	VSS
After Change	P11	VCC