

[Upgrade to revision]

R20TS0683EJ0100

Rev.1.00

Programming GUI for PG-FP6 Flash Memory Programmer

Apr. 13, 2021

(FP6 Terminal) V1.05.02

Overview

The "FP6 Terminal", a programming GUI for the PG-FP6 flash memory programmer has been revised from V1.05.01 to V1.05.02. For an overview of the PG-FP6, refer to the following URL:

<https://www.renesas.com/pg-fp6>

1. Items Revised

1.1 Addition of Supported Devices

Support for the following devices has been added.

(1) RL78 family

Group	Part name
RL78/G23	R7F100GAF, R7F100GAG, R7F100GBF, R7F100GBG, R7F100GCF, R7F100GCG, R7F100GEF, R7F100GEG, R7F100GFF, R7F100GFG, R7F100GFN, R7F100GGF, R7F100GGG, R7F100GGN, R7F100GJF, R7F100JGJ, R7F100GJN, R7F100GLF, R7F100GLG, R7F100GLN, R7F100GMG, R7F100GMN, R7F100GPG, R7F100GPN, R7F100GSN

1.2 Improvements to Functionality

We have improved the following.

(1) Correction of connection error message

The following has newly been added: "ERROR: 004 No response". This "ERROR: 004" occurs when there is no response at the initial communication with the target MCU. Addition of this error allows you to check if communication with the MCU proceeds at all and helps you to narrow down the location of the problem.

With this change, the existing "ERROR: 014" is discontinued and replaced by "ERROR: 004".

2. Updating Your Product

For FP6 Terminal, online updating is available free of charge. Download the installer from the URL below to install the program. (The installer will be available from April 13.)

<https://www.renesas.com/software-tool/pg-fp6#documents>

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Apr.13.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/