

[Upgrade to revision]

R20TS0730EJ0100

Rev.1.00

Jul. 16, 2021

Solution Toolkit

QE for Capacitive Touch[RA,RL78,Synergy]:

Development Assistance Tool for Capacitive Touch Sensor V1.4.1

Overview

The products in the title has been revised and its version number has been changed as follows.

- RA, RL78, Renesas Synergy™ QE for Capacitive Touch[RA,RL78, Synergy]: From V1.4.0 to V1.4.1

1. Version to Be Updated

- RA, RL78 Family QE for Capacitive Touch[RA,RL78, Synergy]V1.4.1.

How to check the version: In e² studio, select [Help] and then [e² studio Installation Details],

open the [Installed Software] tab,

and then check the version of Renesas QE for Capacitive Touch[RA, RL78, Synergy].

2. Items Revised

The major revision points are as follows. For details and how to install the product, refer to the following release note.

- QE for Capacitive Touch[RA, RL78,] V1.4.1 Release Note

<https://www.renesas.com/search?keywords=r20ut5005>

2.1 Description of Modification

The problems regarding the points below have been fixed.

- (1) RENESAS TOOL NEWS Document number R20TS0722EJ0100

1. Notes on using either three RA families (RA4M2, RA4M3 and RA6M5).

Applicable devices: RA4M2 group, RA4M3 group, and RA6M5 groups

For details about the problems, refer to the following URL.

<https://www.renesas.com/search?keywords=r20ts0722>

3. Obtaining the Product

Download the installer for QE for Capacitive Touch[RA, RL78, Synergy] V1.4.1 from the following URL:

<https://www.renesas.com/qe-capacitive-touch>

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.16.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/