

## Supplemental Information

This notice describes the differences between the updated version (Version 10, dated August 20, 2009) and its previous version (Version 9, dated October 29, 2008) of the IDT82P2282 Data Sheet. It helps readers to identify the changes when the data sheet is upgraded.

## Revision History

Revision Date	PCN Number (if applicable)	Date Code	Changed Items
August 20, 2009	-	-	32-31
October 29, 2008	-	-	30-29
Feb 26, 2008	-	-	28
May 31, 2007	-	-	27
April 6, 2007	-	-	26-17
August 1, 2006	-	-	16
April 12, 2006	-	-	15-12
September 1, 2004	-	-	11 ~ 1

## Changed Items

### Aug 20, 2009

**Item 32:** Added clock recovery bullet point in APPLICATIONS portion. (Page 12)

**Item 31:** Added clock recovery paragraph in section '3.12 BIT-ORIENTED MESSAGE RECEIVER'. (Page 59)

### Oct 29, 2008

**Item 30:** Added SSM bullet point in FEATURES portion. (Page 12)

**Item 29:** Added SSM paragraph in section '3.12 BIT-ORIENTED MESSAGE RECEIVER'. (Page 59)

### Feb 26, 2008

**Item 28:** Updated Figure 21~24 and Figure 28~31 to clarify the F-bit in T1/J1 mode. (Pages 68, 69, 76, 77)

### May 31, 2007

**Item 27:** Added E1 Reference Clock Output Control (03EH, 13EH) register. (Pages 241, 265)

### April 6, 2007

**Item 26:** Removed the functional descriptions of the SS7 protocol support. (Pages 54,84, 193, 199, 201, 309, 316)

**Item 25:** Added the section '3.2.1 Line Monitor'. (Pages 24, 25, 26)

**Item 24:** Changed the E1 mode 'CRCM, SIGEN, GENCRC' bite control table. (Page 293)

**Item 23:** Changed the figure 'Read Operation In SPI Mode' and figure 'Write Operation In SPI Mode'. (Page 107)

**Item 22:** Added line driver set to '3.27.2.6 Analog Loopback'. (Page 102)

**Item 21:** Changed the paragraph about transmit clock slave mode and transmit clock master mode. (Page 72)

**Item 20:** Changed the paragraph about non-multiplexed mode. (Pages 70, 72)

**Item 19:** Changed the paragraph about receive clock slave mode and receive clock master mode. (Page 65)

**Item 18:** Added bit 'REFH\_LOS' row to table 5. (Page 27)

**Item 17:** Changed REFA\_OUT and REFB\_OUT pin description. (Page 18)

## August 1, 2006

**Item 16:** Changed package characteristics from PF to PK. (Page 381)

## April 12, 2006

**Item 15:** Changed REFA\_OUT and REFB\_OUT pin description. (Page 18)

**Item 14:** Changed description of internal counters update methods. (Pages 48, 50)

**Item 13:** Added T1/J1 Reference Clock Output Control Register (03EH) (Page 150)

**Item 12:** Added green package information (Page 382)

## September 1, 2004

**Item 11:** The description of the DDSINV bit (b3, T1/J1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one 6-bit DDS pattern and this bit is cleared when the inversion is completed. (Page 69, 166)

**Item 10:** The description of the CRCINV bit (b2, T1/J1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one 6-bit CRC pattern and this bit is cleared when the inversion is completed. (Page 69, 166)

**Item 9:** The description of the FsINV bit (b1, T1/J1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one Fs bit in SF and T1 DM formats, invert one Frame Alignment bit in ESF format or invert one Synchronization Fs bit in SLC-96 format and this bit is cleared when the inversion is completed. (Page 166)

**Item 8:** The description of the FtINV bit (b0, T1/J1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one Ft bit in SF, T1 DM and SLC-96 formats and this bit is cleared when the inversion is completed. (Page 166)

**Item 7:** The description of the CRCINV bit (b5, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert all 4 calculated CRC bits in one Sub-Multi-Frame and this bit is cleared when the inversion is completed. (Page 71, 291)

**Item 6:** The description of the CRCPINV bit (b4, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one 6-bit CRC Multi-Frame alignment pattern and this bit is cleared when the inversion is completed. (Page 71, 291)

**Item 5:** The description of the CASPINV bit (b3, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one 4-bit Signaling Multi-Frame alignment pattern and this bit is cleared when the inversion is completed. (Page 71, 291)

**Item 4:** The description of the NFASINV bit (b2, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one NFAS bit and this bit is cleared when the inversion is completed. (Page 71, 291)

**Item 3:** The description of the FASALLINV bit (b1, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one 7-bit FAS pattern and this bit is cleared when the inversion is completed. (Page 71, 291)

**Item 2:** The description of the FAS1INV bit (b0, E1-06FH,...) is changed. A transition from '0' to '1' on this bit will invert one FAS bit and this bit is cleared when the inversion is completed. (Page 291)

**Item 1:** In 'Ordering Information', the package is changed to 'PF'. (Page 370)

## IMPORTANT NOTICE AND DISCLAIMER

RENESAS ELECTRONICS CORPORATION AND ITS SUBSIDIARIES (“RENESAS”) PROVIDES TECHNICAL SPECIFICATIONS AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES “AS IS” AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, WITHOUT LIMITATION, ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT OF THIRD-PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for developers who are designing with Renesas products. You are solely responsible for (1) selecting the appropriate products for your application, (2) designing, validating, and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. Renesas grants you permission to use these resources only to develop an application that uses Renesas products. Other reproduction or use of these resources is strictly prohibited. No license is granted to any other Renesas intellectual property or to any third-party intellectual property. Renesas disclaims responsibility for, and you will fully indemnify Renesas and its representatives against, any claims, damages, costs, losses, or liabilities arising from your use of these resources. Renesas' products are provided only subject to Renesas' Terms and Conditions of Sale or other applicable terms agreed to in writing. No use of any Renesas resources expands or otherwise alters any applicable warranties or warranty disclaimers for these products.

(Disclaimer Rev.1.01 Jan 2024)

### Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

### Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

### Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit [www.renesas.com/contact-us/](http://www.renesas.com/contact-us/).