



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

Errata Notification

EN #: LEN-02-02

Errata Revision #: 0

Issue Date: April 29, 2002

Effective Date: April 29, 2002

Product Affected: IDT74CBTLV3862

ERRATA DETAILS:

ATTACHMENT

☒ Yes ☐ No

☒ Data Sheet Errata

☐ Device Errata

☐ Device Manual Errata

☐ Application Notes Errata

☐ Other (Please Specify)

Characterization data on IDT74CBTLV3862 OE vs. $\overline{\text{OE}}$ disable times
requires two sets of specifications be shown in data sheet.
(Please see the attachment for the detail).

IDT Web Site Location:

http://www.idt.com/products/pages/Bus_Switches.html

CUSTOMER NOTIFICATION:

As a result of Errata listed above, IDT has decided to notify you through this Errata Notification.
We recommend you to review this notification in details prior to the use of affected product in your application.
Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone #: _____

Title: _____

Fax #: _____

CUSTOMER COMMENTS:



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

Attachment for Errata # LEN-02-02

Switching Characteristics

OLD TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V +/- 0.3V	
		Min	Max	Min	Max
Tdis	Output Disable Time $\overline{OE}$ or OE to A or B	1ns	5ns	1ns	5ns

NEW TABLE

Symbol	Parameter	Vcc = 2.5 +/- 0.2V		Vcc = 3.3V +/- 0.3V	
		Min	Max	Min	Max
Tdis	Output Disable Time $\overline{OE}$ to A or B	1ns	5ns	1ns	5ns
Tdis	Output Disable Time OE to A or B	1ns	5ns	1ns	6ns