



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE# CQ-15-02

ISSUE DATE: May 5, 2015

LAST BUY DATE: May 5, 2016

LAST SHIP DATE: Aug 5, 2016

REASON FOR DISCONTINUANCE:

A manufacturing related issue requires IDT to discontinue these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at www.IDT.com or the marketing contact listed below:

NET

clocks@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Reason for Discontinuation	Product Group
MPC961PAC	None	None	NA	Global Foundry discontinuance	NET
MPC961PACR2	None	None	NA	Global Foundry discontinuance	NET
MPC942CAC	None	83940DYLF	Available now	Global Foundry discontinuance	NET
MPC942CACR2	None	83940DYLF	Available now	Global Foundry discontinuance	NET
MPC940LAC	83940DYLF	None	Available now	Global Foundry discontinuance	NET
MPC940LACR2	83940DYLF	None	Available now	Global Foundry discontinuance	NET
MPC9315AC	None	None	NA	Global Foundry discontinuance	NET
MPC9315ACR2	None	None	NA	Global Foundry discontinuance	NET