



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE# CQ-17-05

ISSUE DATE: November 28, 2017

LAST BUY DATE: November 28, 2018

LAST SHIP DATE: February 28, 2019

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at www.IDT.com or the marketing contact listed below:

MIP

Paul Barton
408-284-8306
paul.barton@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
4DB0124KB1AVG	None	4DB0226KA3AVG	Available now	MIP
4DB0124KB1AVG8	None	4DB0226KA3AVG8	Available now	MIP
93V855AGLF	None	None	N/A	MIP
93V855AGLFT	None	None	N/A	MIP
95V857AGILF	None	None	N/A	MIP
95V857AGILFT	None	None	N/A	MIP
95V857AGLF	None	None	N/A	MIP
95V857AGLFT	None	None	N/A	MIP
95V857AHLF	None	None	N/A	MIP
95V857AHLFT	None	None	N/A	MIP
95V857AKLF	None	None	N/A	MIP
95V857AKLFT	None	None	N/A	MIP
97U2A845AHLF	None	None	N/A	MIP
97U2A845AHLFT	None	None	N/A	MIP
97U877AKLF	98ULPA877AKLF	None	Available now	MIP
97U877AKLFT	98ULPA877AKLFT	None	Available now	MIP
SSTUA32864BHLF	None	None	N/A	MIP
SSTUA32864BHLFT	None	None	N/A	MIP
SSTVA16857AGLF	None	None	N/A	MIP
SSTVA16857AGLFT	None	None	N/A	MIP
SSTVF16857AGLF	None	None	N/A	MIP
SSTVF16857AGLFT	None	None	N/A	MIP
SSTVF16859BKLF	None	None	N/A	MIP
SSTVF16859BKLFT	None	None	N/A	MIP
TSE2002GB2A1NRG	None	None	N/A	MIP
TSE2002GB2A1NRG8	None	None	N/A	MIP