



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: **L-04-01R1**

Last Buy Date: April 26, 2005

Issue Date: April 26, 2004

Last Ship Date: July 26, 2005
(3 months after last buy date)

PRODUCT(S) AFFECTED:
(List Replacement Part #(s), if any)

ATTACHMENT ☒ Yes ☐ No

See attached list.

Revision "R1": Revised last buy date and last ship date on select products, marked with "***".
Please see attachment for details.

REASON FOR DISCONTINUANCE:

☐ Replace slower speed with faster speed offerings

☐ Other: _____

☐ Obsolete Fab Technology / Process

☐ Obsolete Assembly Technology / Process

☐ Obsolete Package / Material

☒ Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____

E-Mail Address: _____

Name/Date: _____

Phone#: _____

Title: _____

Fax#: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____

Date: _____



Integrated Device Technology, Inc.
2975 Stender Way, Santa Clara, CA - 95054
Phone #: (408) 727-6116 Fax #: (408) 727-2328

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN# L-04-01R1 Attachment

Affected IDT Part #	Replacement Part #
IDT54FCT821ALB	No Replacement
IDT54FCT821BLB	No Replacement
IDT54FCT821ADB	No Replacement
IDT54FCT821BDB	No Replacement
IDT5962-88608013A	No Replacement
IDT5962-88608023A	No Replacement
IDT5962-8860801LA	No Replacement
IDT5962-8860802LA	No Replacement
IDT74ALVC244Q	No Replacement
IDT74ALVC244PG	No Replacement
IDT74ALVC244SO	No Replacement
IDT74ALVC244PY	No Replacement
IDT74ALVCH16244PF	No Replacement
IDT74FCT821ASO	No Replacement
IDT74FCT821BSO	No Replacement
IDT74FCT833ASO	No Replacement
IDT74FCT833BSO	No Replacement
*** IDT74LVC07ADC	No Replacement
*** IDT74LVC07APG	No Replacement
*** IDT74LVC07APY	No Replacement
IDT74LVC08ADC	No Replacement
IDT74LVC08APG	No Replacement
IDT74LVC08APY	No Replacement
IDT74LVC163APG	No Replacement
IDT74LVC373AQ	No Replacement
IDT74LVC373APG	No Replacement
IDT74LVC373ASO	No Replacement
IDT74LVC373APY	No Replacement
IDT74LVCH16652APA	No Replacement
IDT74LVCH16652APV	No Replacement
*** IDT74LVCR2245AQ	No Replacement
*** IDT74LVCR2245APG	No Replacement
*** IDT74LVCR2245ASO	No Replacement
*** IDT74LVCR2245APY	No Replacement

Note: Due to declined inventory, IDT cannot support the last buy orders on select products marked with "***". Therefore, there is no last buy or ship date for these select products. These are multisourced devices, and are available from other commodity device manufacturers.