



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: <u>M-07-01</u>	Last Buy Date: <u>January 25, 2008</u>
Issue Date: <u>July 25, 2007</u>	Last Ship Date: <u>April 25, 2008</u> (3 months after last buy date)

Contact: **Paul Barton**
 Title: **Marketing Manager - DIMM Products**
 Phone #: **(408) - 284-8306**
 Fax #: **(408) - 284-2774**
 E-mail: Paul.Barton@idt.com

PRODUCT(S) AFFECTED: _____ **ATTACHMENT** Yes No
(List Replacement Part #(s), if any)

Selected DIMM products will be discontinued.

Please see Attachment I for the discontinued part# and recommended replacement part # list.

REASON FOR DISCONTINUANCE:

Replace slower speed with faster speed offerings Other: _____
 Obsolete Fab Technology / Process _____
 Obsolete Assembly Technology / Process _____
 Obsolete Package / Material _____
 Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____	E-Mail Address: _____
Name/Date: _____	Phone#: _____
Title: _____	Fax# : _____
CUSTOMER COMMENTS: _____	

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-07-01

Discontinued Part#	Recommended Replacement Part#	Comment
ICS162830AG	IDT74ALVCHS162830DFG	
ICS162834AG	None	
ICS162835AG	ICS162835AGLF	
ICS16835AGLF	None	
ICS2509BG	IDTCSP2510CPG	
ICS2509CG	IDTCSP2510CPG	
ICS2509CGLF	IDTCSP2510CPGG	
ICS2509DG	IDTCSP2510CPG	
ICS2509DGLF	IDTCSP2510CPGG	
ICS2510BG	IDTCSP2510CPG	
ICS2510DG	IDTCSP2510CPG	
ICS2510DGI	IDTCSP2510CPGI	
ICS91857AL	None	
ICS93857AG	IDTCSP2510CPG	
ICS93V847AG	None	
ICS93V847AGLF	None	
ICS93V850AG	ICS95V850AG	
ICS93V850AGLF	ICS95V850AGLF	
ICS93V850CG	ICS95V850AG	
ICS93V850DG	ICS95V850AG	
ICS93V857BG-025	ICS95V857AGLF	
ICS93V857BG-125	ICS95V857AGLF	
ICS93V857BG-125LF	ICS95V857AGLF	
ICS93V857BG-130	ICS95V857AGLF	
ICS93V857BG-130LF	ICS95V857AGLF	
ICS93V857BG-130LN	ICS95V857AGLF	
ICS93V857BK-130	ICS95V857AKLF	
ICS93V857BL-025	ICS95V857ALLF	
ICS93V857BL-125	ICS95V857ALLF	
ICS93V857BL-130	ICS95V857ALLF	
ICS95V2F857AG	ICS95V2F857AGLF	
ICS95V2F857AH	ICS95V2F857AHLF	Lead Free version, Higher reflow temperature required
ICS95V2F857AK	ICS95V2F857AKLF	
ICS95V2F857AL	None	
ICS95V2F857ALLF	None	
ICS95V850AGI	ICS95V850AG	Commercial Grade
ICS95V857AG-130	ICS95V857AG-130LF	
ICS95V857AG-SM0	None	
ICS95V857AK-130	ICS95V857AK-130LF	
ICS95V857AL-130	None	
ICS95V857AL-130LF	None	
ICS95V857ALI	None	
ICS95V857CG	ICS95V857CGLF	

Notes: For T & R (shipping method) suffix "8" and "T" is added to the IDT and ICS part# respectively



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-07-01

Discontinued Part#	Recommended Replacement Part#	Comment
ICS95V857CK	ICS95V857CKLF	
ICS95V860AH	None	
ICS95V860AHLF	None	
ICS95VLP857AG	ICS95VLP857AGLF	
ICS95VLP857AH	ICS95VLP857AHLF	Lead Free version, Higher reflow temperature required
ICS95VLP857AK	ICS95VLP857AKLF	
ICS95VLP857AL	None	
ICS95VLP857ALLF	None	
ICS97U870AHI	ICS97U870AH	Commercial Grade
ICS97U877AKI	ICS98ULPA877AKLF	Commercial Grade
ICS97U877BH	ICS98ULPA877AHLF	Lead Free version, Higher reflow temperature required
ICS97UA877AH	ICS98ULPA877AHLF	Lead Free version, Higher reflow temperature required
ICS97UA877AHLF	ICS98ULPA877AHLF	
ICS97ULP877AK	ICS98ULPA877AKLF	
ICS97ULP877AKLF	ICS98ULPA877AKLF	
ICS97ULP877BK	ICS98ULPA877AKLF	
ICS97ULP878AH	ICS98ULPA877AHLF	Lead Free version, Higher reflow temperature required
ICS97ULP878AHLF	ICS98ULPA877AHLF	
ICS97ULP878AK	ICS98ULPA877AKLF	
ICS97ULP878AKLF	ICS98ULPA877AKLF	
ICS97ULP878BH	ICS98ULPA877AHLF	Lead Free version, Higher reflow temperature required
ICS97ULP878BHLF	ICS98ULPA877AHLF	
ICS97ULP878BK	ICS98ULPA877AKLF	
ICS97ULP878BKLF	ICS98ULPA877AKLF	
ICS97ULPA877AH	ICS98ULPA877AHLF	Lead Free version, Higher reflow temperature required
ICSSSTU32864AH	IDT74SSTUBF32866BBFG	Lead Free version, Higher reflow temperature required
ICSSSTUA32864BH	IDT74SSTUBF32866BBFG	Lead Free version, Higher reflow temperature required
ICSSSTUA32864CH	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
ICSSSTUA32864CHLF	IDT74SSTUBF32866BBFG	
ICSSSTUA32866AHLF	ICSSSTUAF32866BHLF	
ICSSSTUA32866BHMLF	None	
ICSSSTUA32866ASHLF	None	
ICSSSTUA32866BH	ICSSSTUAF32866BHLF	Lead Free version, Higher reflow temperature required
ICSSSTUA32866BHMLF	ICSSSTUAF32866BHLF	Package size
ICSSSTUA32866CH	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
ICSSSTUA32866DHLF	IDT74SSTUBF32866BBFG	
ICSSSTUA32S865AHLF	ICSSSTUAF32865BHLF	
ICSSSTUA32S865BHLF	ICSSSTUAF32865AHLF	
ICSSSTUA32S868AH	ICSSSTUAF32868AHLF	Lead Free version, Higher reflow temperature required
ICSSSTUA32S868AHLF	ICSSSTUAF32868AHLF	
ICSSSTUA32S868BHLF	ICSSSTUAF32868AHLF	
ICSSSTUA32S868CHLF	ICSSSTUAF32868AHLF	
ICSSSTUA32S869AHLF	ICSSSTUAF32869AHLF	

Notes: For T & R (shipping method) suffix "8" and "T" is added to the IDT and ICS part# respectively



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-07-01

Discontinued Part#	Recommended Replacement Part#	Comment
ICSSSTUA32S869BHLF	ICSSSTUAF32869AHLF	
ICSSSTUB32864AH	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
ICSSSTUB32S865AHLF	IDT74SSTUBF32865ABKG	
ICSSSTUB32S868AHLF	IDT74SSTUBF32868ABKG	
ICSSSTUBV32866AHLF	IDT74SSTUBF32866BBFG	
ICSSSTUF32864AH	IDT74SSTU32864CBFG	Green version, Higher reflow temperature required
ICSSSTUF32864BH	IDT74SSTU32864CBFG	Green version, Higher reflow temperature required
ICSSSTUF32864CH	IDT74SSTU32864CBFG	Green version, Higher reflow temperature required
ICSSSTUF32864EH	IDT74SSTU32864CBFG	Green version, Higher reflow temperature required
ICSSSTUF32865AH	ICSSSTUAF32865AHLF	Lead Free version, Higher reflow temperature required
ICSSSTUF32865AHLF	ICSSSTUAF32865AHLF	
ICSSSTUF32866AH	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
ICSSSTUF32866EH	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
ICSSSTUF32868AH	IDT74SSTUBF32868ABKG	Green version, Higher reflow temperature required
ICSSSTUF32868AHLF	IDT74SSTUBF32868ABKG	
ICSSSTV16857CGLF	ICSSSTVF16857AGLF	
ICSSSTV16857CL	None	
ICSSSTV16859AG	ICSSSTVA16859CGLF	
ICSSSTV16859CG	ICSSSTVA16859CGLF	
ICSSSTV16859CK	ICSSSTVA16859CKLF	
ICSSSTV32852AH	ICSSSTVA32852AHLF	Lead Free version, Higher reflow temperature required
ICSSSTV32852AHLF	ICSSSTVA32852AHLF	
ICSSSTV32852BH	ICSSSTVA32852AHLF	Lead Free version, Higher reflow temperature required
ICSSSTV32852BHLF	ICSSSTVA32852AHLF	
ICSSSTV32852CH	ICSSSTVA32852AHLF	Lead Free version, Higher reflow temperature required
ICSSSTV32852CHLF	ICSSSTVA32852AHLF	
ICSSSTVA16857AL	ICSSSTVF16857ALLF	
ICSSSTVA16857ALLF	ICSSSTVF16857ALLF	
ICSSSTVA16859AK	ICSSSTVA16859CKLF	
ICSSSTVA16859BG	ICSSSTVA16859CGLF	
ICSSSTVA16859BGLF	ICSSSTVA16859CGLF	
ICSSSTVA16859BK	ICSSSTVA16859CKLF	
ICSSSTVA16859CG	ICSSSTVA16859CGLF	
ICSSSTVA16859CK	ICSSSTVA16859CKLF	
ICSSSTVA16859DKLF	ICSSSTVA16859CKLF	
ICSSSTVA32852BH	ICSSSTVA32852AHLF	Lead Free version, Higher reflow temperature required
ICSSSTVA32852BHLF	ICSSSTVA32852AHLF	
ICSSSTVA32852CH	ICSSSTVA32852AHLF	Lead Free version, Higher reflow temperature required
ICSSSTVA32852CHLF	ICSSSTVA32852AHLF	
ICSSSTVA32852DHLF	ICSSSTVA32852AHLF	
ICSSSTVF16857AGLN	ICSSSTVF16857AGLF	
ICSSSTVF16859BK	ICSSSTVA16859CKLF	
ICSVF2509BG	None	

Notes: For T & R (shipping method) suffix "8" and "T" is added to the IDT and ICS part# respectively



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-07-01

Discontinued Part#	Recommended Replacement Part#	Comment
ICSVF2509BGLN	None	
ICSVF2510BGI	ICSVF2510BGLFI	
IDT74ALVCF162835APV	None	
IDT74SSTU32864DBF	IDT74SSTU32864CBFG	Green version, Higher reflow temperature required
IDT74SSTU32865BK	IDT74SSTUBF32865ABKG	Green version, Higher reflow temperature required
IDT74SSTU32868BBKG	IDT74SSTUBF32868ABKG	
IDT74SSTU32868BKG	IDT74SSTUBF32868ABKG	
IDT74SSTU32869BKG	IDT74SSTUBF32869ABKG	
IDT74SSTU32D869BKG	IDT74SSTUBF32869ABKG	
IDT74SSTUA32864BF	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
IDT74SSTUA32866ABFG	IDT74SSTUBF32866BBFG	
IDT74SSTUA32866BBFG	IDT74SSTUBF32866BBFG	
IDT74SSTUA32866BF	IDT74SSTUBF32866BBFG	Green version, Higher reflow temperature required
IDT74SSTUA32866CBFG	IDT74SSTUBF32866BBFG	
IDT74SSTUA32S868BKG	IDT74SSTUBF32868ABKG	
IDTCSP857CPF	None	
IDTCSP857DPF	None	
IDTCSPU877BBV	IDTCSPUA877ABVG	Green version, Higher reflow temperature required
IDTCSPU877BBVG	IDTCSPUA877ABVG	
IDTCSPU877BNL	ICS98ULPA877AKLF	
IDTCSPU877BNLG	ICS98ULPA877AKLF	
IDTCSPU877DBV	IDTCSPU877DBVG	Green version, Higher reflow temperature required
IDTCSPU877DNL	IDTCSPU877DNLG	
IDTCSPUA877BV	IDTCSPUA877ABVG	Green version, Higher reflow temperature required
IDTCSPUA878BVG	IDTCSPUA877ABVG	
IDTCSPUE877BVG	IDTCSPUA877ABVG	

Notes: For T & R (shipping method) suffix "8" and "T" is added to the IDT and ICS part# respectively