



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: M-11-01 Last Buy Deadline for Submission of Order: 9-Dec-2012

Issue Date: 9-Dec-2011 Last Eligible Ship Date: 9-Mar-2013

Contact: Paul Barton
 Title: Marketing Manager - DIM Products
 Phone #: 408-284-8306
 Fax #: 408-360-1748
 E-mail: paul.barton@idt.com

PRODUCT(S) AFFECTED: ATTACHMENT Yes No
(List Replacement Part #(s), if any)

Selective DIM parts as listed in Attachment I will be discontinued.

REASON FOR DISCONTINUANCE:

- Replace slower speed with faster speed offerings Other: _____
- Obsolete Fab Technology / Process _____
- Obsolete Assembly Technology / Process _____
- Obsolete Package / Material _____
- Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
 Name/Date: _____ Phone#: _____
 Title: _____ Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-11-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
162830AG	74ALVCHS162830DFG	74SSTVN16859PAG8	SSTVA16859CGLFT
162830AGT	74ALVCHS162830DFG8	91857AG	91857AGLF
162835AGLF	74ALVCF162835APAG	91857AGT	91857AGLFT
162835AGLFT	74ALVCF162835APAG8	93V855AG	93V855AGLF
2510CG	2510CGLF	93V855AGT	93V855AGLFT
2510CGT	2510CGLFT	95V157AGI	95V157AGLF
74SSTU32864ABFG	74SSTU32864CBFG	95V157AGIT	95V157AGLFT
74SSTU32864ABFG8	74SSTU32864CBFG8	95V2F857AGLF	none
74SSTU32864DBFG	74SSTU32864CBFG	95V2F857AGLFT	none
74SSTU32864DBFG8	74SSTU32864CBFG8	95V842AF	95V842AFLF
74SSTU32865BKG	74SSTUBF32865ABKG	95V842AFT	95V842AFLFT
74SSTU32865BKG8	74SSTUBF32865ABKG8	95V847AGI	95V847AGLF
74SSTU32D868BKG	74SSTUBF32868ABKG	95V847AGIT	95V847AGLFT
74SSTU32D868BKG8	74SSTUBF32868ABKG8	95V850AG	95V850AGLF
74SSTUA32864BFG	74SSTUBF32866BBFG	95V850AGT	95V850AGLFT
74SSTUA32864BFG8	74SSTUBF32866BBFG8	95V857AG-130LF	95V857AGLF
74SSTUA32866MBFG	74SSTUBF32866BBFG	95V857AG-130LFT	95V857AGLFT
74SSTUA32866MBFG8	74SSTUBF32866BBFG8	95V857AGG-110	95V857AGLF
74SSTUB32864ABFG	74SSTUBF32866BBFG	95V857AGG-110T	95V857AGLFT
74SSTUB32864ABFG8	74SSTUBF32866BBFG8	95V857AK	95V857AKLF
74SSTUB32866ABFG	74SSTUBF32866BBFG	95V857AK-130LF	95V857AKLF
74SSTUB32866ABFG8	74SSTUBF32866BBFG8	95V857AK-130LFT	95V857AKLFT
74SSTUB32866BBFG	74SSTUBF32866BBFG	95V857AKT	95V857AKLFT
74SSTUB32866BBFG8	74SSTUBF32866BBFG8	95V857AL	95V857ALLF
74SSTUB32866MBFG	74SSTUBF32866BBFG	95V857ALT	95V857ALLFT
74SSTUB32866MBFG8	74SSTUBF32866BBFG8	95V857CKLF	CSPT857CNLG
74SSTUB32S865BKG	74SSTUBF32865ABKG	95V857CKLF8	CSPT857CNLG8
74SSTUB32S865BKG8	74SSTUBF32865ABKG8	95V860AHLF	none
74SSTUB32S868BKG	74SSTUBF32868ABKG	95V860AHLFT	none
74SSTUB32S868BKG8	74SSTUBF32868ABKG8	95VLP857AKLF	95VLP857AGLF
74SSTUBF32865ABK	74SSTUBF32865ABKG	95VLP857AKLFT	95VLP857AGLFT
74SSTUBF32865ABK8	74SSTUBF32865ABKG8	97U870AH	none
74SSTUBF32866CBFG	74SSTUBF32866BBFG	97U870AHT	none
74SSTUBF32866CBFG8	74SSTUBF32866BBFG8	97U870AK	none
74SSTUBH32865ABKG	none	97U870AKT	none
74SSTUBH32865ABKG8	none	97U877AH	98ULPA877AHLF
74SSTV16859PAG	SSTVA16859CGLF	97U877AHT	98ULPA877AHLFT
74SSTV16859PAG8	SSTVA16859CGLFT	97U877AK	98ULPA877AKLF
74SSTVN16859CNLG	SSTVA16859CKLF	97U877AKT	98ULPA877AKLFT
74SSTVN16859CNLG8	SSTVA16859CKLFT	97ULP877AH	98ULPA877AHLF
74SSTVN16859CPAG	SSTVA16859CGLF	97ULP877AHLF	98ULPA877AHLF
74SSTVN16859CPAG8	SSTVA16859CGLFT	97ULP877AHLFT	98ULPA877AHLFT
74SSTVN16859NLG	SSTVA16859CKLF	97ULP877AHT	98ULPA877AHLFT
74SSTVN16859NLG8	SSTVA16859CKLFT	97ULP877BH	98ULPA877AHLF
74SSTVN16859PAG	SSTVA16859CGLF	97ULP877BHT	98ULPA877AHLFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-11-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
97ULP877BKLF	98ULPA877AKLF	SSTUF32864EHLFT	74SSTU32864CBFG8
97ULP877BKLFT	98ULPA877AKLFT	SSTUF32866AHLF	74SSTUBF32866BBFG
98UAE877AHLF	98ULPA877AHLF	SSTUF32866AHLFT	74SSTUBF32866BBFG8
98UAE877AHLFT	98ULPA877AHLFT	SSTUF32866EHLF	74SSTUBF32866BBFG
CSPT857DNLG	CSPT857CNLG	SSTUF32866EHLFT	74SSTUBF32866BBFG8
CSPT857DNLG8	CSPT857CNLG8	SSTV16857AGLF	SSTVA16857AGLF
MPC96877VK	98ULPA877FHFLF	SSTV16857AGLFT	SSTVA16857AGLFT
MPC96877VKR2	98ULPA877FHFLF	SSTV16857CG	SSTVA16857AGLF
SSTU32864AHLF	74SSTU32864CBFG	SSTV16857CGLN	SSTVA16857AGLF
SSTU32864AHLFT	74SSTU32864CBFG8	SSTV16857CGLNT	SSTVA16857AGLFT
SSTUA32864BHMLF	74SSTUBF32866BBFG	SSTV16857CGT	SSTVA16857AGLFT
SSTUA32866BHLF	74SSTUBF32866BBFG	SSTV16859CGLF	SSTVA16859CGLF
SSTUA32866BHLFT	74SSTUBF32866BBFG8	SSTV16859CGLFT	SSTVA16859CGLFT
SSTUA32868CHLF	74SSTUBF32868ABKG	SSTV16859CKLF	SSTVA16859CKLF
SSTUA32868CHLFT	74SSTUBF32868ABKG8	SSTV16859CKLFT	SSTVA16859CKLFT
SSTUAF32866BHLF	74SSTUBF32866BBFG	SSTVA16857AG	SSTVA16857AGLF
SSTUAF32866BHLFT	74SSTUBF32866BBFG8	SSTVA16857AGT	SSTVA16857AGLFT
SSTUAF32868BHLF	74SSTUBF32868ABKG	SSTVA16859AG	SSTVA16859CGLF
SSTUAF32868BHLFT	74SSTUBF32868ABKG8	SSTVA16859AGLF	SSTVA16859CGLF
SSTUAF32869AHLF	74SSTUBF32869ABKG	SSTVA16859AGLFT	SSTVA16859CGLFT
SSTUAF32869AHLFT	74SSTUBF32869ABKG8	SSTVA16859AGT	SSTVA16859CGLFT
SSTUB32864BHLF	74SSTUBF32866BBFG	SSTVA16859BKLF	SSTVA16859CKLF
SSTUB32864BHLFT	74SSTUBF32866BBFG8	SSTVA16859BKLFT	SSTVA16859CKLFT
SSTUB32866CHLF	74SSTUBF32866BBFG	SSTVA32852AH	SSTVA32852AHLF
SSTUB32866CHLFT	74SSTUBF32866BBFG8	SSTVA32852AHT	SSTVA32852AHLFT
SSTUB32871AHLF	SSTUB32872AHMLF	SSTVF16857AG	SSTVA16857AGLF
SSTUB32871AHLFT	SSTUB32872AHMLFT	SSTVF16857AGT	SSTVA16857AGLFT
SSTUB32871AHMLF	SSTUB32872AHMLF	SSTVF16857AL	SSTVA16857AGLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16857ALLF	SSTVA16857AGLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16857ALLFT	SSTVA16857AGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16857ALT	SSTVA16857AGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859AG	SSTVA16859CGLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859AGLFT	SSTVA16859CGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859AGT	SSTVA16859CGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859AK	SSTVA16859CKLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859AKT	SSTVA16859CKLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859BG	SSTVA16859CGLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859BGLF	SSTVA16859CGLF
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859BGLFT	SSTVA16859CGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	SSTVF16859BGT	SSTVA16859CGLFT
SSTUB32871AHMLFT	SSTUB32872AHMLFT	VF2510BG	CSP2510DPGG
SSTUB32871AHMLFT	SSTUB32872AHMLFT	VF2510BGILF	CSP2510DPGGI
SSTUB32871AHMLFT	SSTUB32872AHMLFT	VF2510BGILFT	CSP2510DPGGI8
SSTUB32871AHMLFT	SSTUB32872AHMLFT	VF2510BGLF	CSP2510DPGG



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road, San Jose, CA 95138
Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-11-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
VF2510BGLFT	CSP2510DPGG8	VF2510BGLNT	CSP2510DPGG8
VF2510BGLN	CSP2510DPGG	VF2510BGT	CSP2510DPGG8