

PRODUCT DISCONTINUANCE # U-14-02

ISSUE DATE: December 3, 2014

LAST TIME BUY DATE: December 3, 2015

LAST TIME SHIP DATE: March 3, 2016

REASON FOR DISCONTINUANCE:

Manufacturing related issues requires IDT to discontinue the below list of products.

There are no IDT part numbers available as drop in or suggested functional replacements.

Customer should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuation Notice. They may also contact their local IDT Sales Office listed on the IDT website at www.idt.com or the Marketing contact listed below. The affected parts lists show the applicable product marketing group.

Product Group Contact Information

MMT Victor Abarca (Victor.Abarca@idt.com) Phone# (408) 284-6578

Last time buy orders may be submitted any time prior to the last time buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.

Device to be Discontinued	Direct Replacement	Functional replacement	Replacement Part Availability	Reason for Discontinuance	Product Group
MK1491-06RLF	None	None	N/A	Fab Base Discontinued	MMT
MK1491-06RLFTR	None	None	N/A	Fab Base Discontinued	MMT
MK1491-06RILF	None	None	N/A	Fab Base Discontinued	MMT
MK1491-06RILFTR	None	None	N/A	Fab Base Discontinued	MMT