

End Of Life Notice
 Notification – PLC22013
 [01 April 2022]

To: Our Valued Customers

Overview: The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

Affected

Products: Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

Standard Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	01-Oct-22
Last Shipment (LTS)	01-Apr-23
Custom / Proprietary Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	01-Apr-23
Last Shipment (LTS)	01-Oct-23
Manufacturing Discontinuance due to Supplier Discontinuance	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	01-Sep-22
Last Shipment (LTS)	01-Sep-23

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.



Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,
Renesas Electronics



Exact Renesas Part # No other variation is being impacted.	Notice PLC22013 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
EL5162ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5162ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5162ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5162ISZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5163IWZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5163IWZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5164ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5164ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5164ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5164IWZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5164IWZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5165IWZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5165IWZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5171ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5171ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5171ISZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5174ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5174ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5174ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175IYZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175IYZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5175IYZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5177IYZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5177IYZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5177IYZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5203ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5203ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5203IYZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5203IYZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5364ISZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5364ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5364ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5364IUZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance

EL5364IUZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL5364IUZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL8101IWZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL8101IWZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL8101IWZ-TK	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL8302ISZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
EL8302ISZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
HAA9Q-53091ZR5141	4/1/2022	4/1/2023	10/1/2023	None	Manufacturing Discontinuance
HAA9Q-53091ZR5141-T	4/1/2022	4/1/2023	10/1/2023	None	Manufacturing Discontinuance
ISL1220IUZ-T	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL1221IUZ-T	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL1557AIRZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL1557AIRZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL22424WFR16Z	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL22424WFR16Z-TK	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL22424WFV14Z	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL22424WFV14Z-TK	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28194EVAL1Z	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28194FHZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28194FHZ-T7A	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28194FRUZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290EVAL1Z	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290FBZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290FBZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290FRUZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290FUZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28290FUZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL28345FBZ	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28345FBZ-T13	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28345FBZ-T7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28345FBZ-T7A	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28407FBZ	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28407FBZ-T13	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28407FBZ-T7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28407FBZ-T7A	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28408FBZ	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28408FBZ-T13	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28408FBZ-T7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28408FBZ-T7A	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance

ISL28417FBBZ	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T13	Manufacturing Discontinuance
ISL28417FBBZ-T13	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T13	Manufacturing Discontinuance
ISL28417FBBZ-T7	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T7	Manufacturing Discontinuance
ISL28417FBBZ-T7A	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T7A	Manufacturing Discontinuance
ISL28417FBZ-T13	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T13	Manufacturing Discontinuance
ISL28417FBZ-T7	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T7	Manufacturing Discontinuance
ISL28417FBZ-T7A	4/1/2022	10/1/2022	4/1/2023	ISL28417FVBZ-T7A	Manufacturing Discontinuance
ISL28417FVBZ-T13	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28417FVBZ-T7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL28417FVBZ-T7A	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL59110IEZ-T7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL59110IEZ-T7R5235	4/1/2022	4/1/2023	10/1/2023	None	Manufacturing Discontinuance
ISL59830IAZ	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL59830IAZ-T13	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL59830IAZ-T7	4/1/2022	9/1/2022	9/1/2023	None	Manufacturing Discontinuance
ISL95810WIRT8Z	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL95810WIRT8Z-T	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL95810WIU8Z	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
ISL95810WIU8Z-T	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
TW2828-BA2-CR	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
X5043PIZ	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
X5043PIZ-2.7	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
X5043PIZ-2.7A	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance
X5043PZ	4/1/2022	10/1/2022	4/1/2023	None	Manufacturing Discontinuance